

U. S. Department of Agriculture
FOREST SERVICE

P

Chippewa NATIONAL FOREST E-9
CORNERS OF THE PUBLIC SURVEY

T. 150 R. 27 S. Mer.
Sec. Corner common to Sections
4, 5, 8, and 9

Corner consists of a wood post (not) in place
State condition good

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

L. D. Johnson.

(Signature)

1-15-34
(Date)

Surveyor
(Title)


E-9

Corner again.
CAN be located from
Road Notes.

Give any further facts which will aid in finding this
1948. chains distant.

from which this Corner bears N 30° W.

side of Road
tree 6 inches diameter, on the South.
Metal Location Poster is on a Bass Wood.



(Make sketch of topography near Corner)

T. 15 S R. 27 E Mer. E-9