

U. S. Department of Agriculture
FOREST SERVICE

G12
posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 27 5 P Mer.
1/6 N 8 Corner common to Sections
_____, _____, _____, and 9

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Edward W. Johnson

(Signature)

June 15 - 1934

(Date)

(Title)

G-12

Corner again. *From the location of the*


Give any further facts which will aid in finding this chains distant.

from which this Corner bears *North 25° 00' W*

side of *Road*

tree inches diameter, on the *South side*

Metal Location Poster is on a *Force Post*



(Make sketch of topography near Corner)

T. 150 N. R. 27 W. 5 Mer. 6-12