

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST R-13

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 27 5 Mer.

Sec Corner common to Sections 21, 22, 23, and 24

Corner consists of a Post (not) in place

State condition good 2" x 2"

Dimensions above ground 30" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species ASPEN ASPEN STR.

Diameter 8" 8"

Bearing S40°W. N85°E

Distance 5 22

Do you believe this to be a genuine Land Office Corner? YES.

If not, why?

Lloyd D. Johnson (Signature)

1-23-34 (Date)


Surveyor (Title)

Lake remains North of
Old Road on North
side of cor. 20 links
from S.W.
Corner again.

Give any further facts which will aid in finding this
chains distant.

From which this Corner bears S 40° W

side of tree
3 inches diameter, on the
Metal Location Poster is on a
S.W. ASPEN



(Make sketch of topography near Corner)

R-13
Mer.

T 150 R 27 5