

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

P

CHIPPEWA NATIONAL FOREST X-17

CORNERS OF THE PUBLIC SURVEY

T. 150N R. 27W 5TH Mer.



1/4 Corner common to Sections
34, and 35

Corner consists of a SPRUCF POST (~~not~~) in place
State condition GOOD

Dimensions above ground 26 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? NO

If not, why? POST TOO NEW.

Harrison Adams
(Signature)

7/26/34
(Date)

see also Binder
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 150N R. 27W 5TH Mer. X-17