

U. S. Department of Agriculture
FOREST SERVICE

9

CHIPPEWA NATIONAL FOREST V-17

CORNERS OF THE PUBLIC SURVEY

T. 152N R. 27W 5TH Mer.

SECTION Corner common to Sections
27, 26, 34, and 35

Corner consists of a NO POST (not) in place
State condition

Dimensions above ground inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

illegible			

Species J. PINE
Diameter 3.149
Bearing S 82° E
Distance 20.4 LINKS

Do you believe this to be a genuine Land Office Corner? yes
If not, why?

Admission Adams
(Signature)

7/24/34
(Date)

Forest Ranger
(Title)

V-17

