

Form 874-B Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

R-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 27 S. Mer. Sec. Corner common to Sections

23, 26, and 27

Corner consists of a POST (not) in place

State condition Marked S-22-S23-S-6-2

Dimensions above ground H. 30" Dia 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species SPRUCE

Diameter 14"

Bearing N 40 W

Distance 68 Chs.

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

J. E. Ames

(Signature)

1-30-34


(Date)

(Title)

R-17

Series of horizontal dashed lines for writing.

Corner again.
Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a
B. T.




(Make sketch of topography near Corner)

T. 150 R. 2
Mer. 8-17

Section Corners 52-23-27 R17

T 150 R 27 Mer. 5^d



Corner is a POST

Height 30"

Dia 4"

Marked 5-22-523

527-526-
T 150 R 27

BEARING TREES

Marks S
23
B.T. _____

Species Spruce _____

Diameter 14" _____

Bearing N4°W _____

Distance 68d _____

Metal poster on B.T.

Remarks:

Date 1-30-34 Signed [Signature]

