

U. S. Department of Agriculture
FOREST SERVICE

R 19

posted

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 150 R. 27 S Mer.

Quarter Corner common to Sections

, 23, and 26

Corner consists of a Post (not) in place

State condition Fallen down

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
S		S	
23		26	

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 26			
BT			

Species Pine

Diameter 2"

Bearing 234°

Distance 356114

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

G. Shevman

(Signature)

1-15-34

(Date)

ENGINEER

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a *Bearing Tree*



(Make sketch of topography near Corner)

T. 150 R. 27 S Mer. R-19