

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST J-19

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 27 Mer. 5

14 Corner common to Sections
11, and 14

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---|---|---|---|
| | | | |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

L. H. Johnson

(Signature)

Surveyor

(Title)


1-10-34

(Date)

Corner again.
CORNER IS IN CENTER of Road.
107. N.E.

Give any further facts which will aid in finding this
324 Hrs. chains distant.
from which this Corner bears S-190 E

side of Road
tree 6 inches diameter, on the North
Metal Location Poster is on a Fence Post



(Make sketch of topography near Corner)

Mer. 5-19

T. 158 R. 27 5