

U. S. Department of Agriculture

FOREST SERVICE

9

CHIPPEWA NATIONAL FOREST P-21

CORNERS OF THE PUBLIC SURVEY

T. 150N R. 27W 5 Mer.

1/4 Corner common to Sections 23, and 24



Corner consists of a (not) in place State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N

W

S

E

NW

SW


SE

NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species BASSAM CEDAR STR.

Diameter 4 8

Bearing N 72 E S 81 E

Distance 81.7 19.4

Do you believe this to be a genuine Land Office Corner? YES

If not, why?

L. C. W. JOHNSON (Signature)

1-10-34 (Date)

SURVEYOR (Title)

CORNER IS 51 KYS EAST
OF WITNESS CORNER CENTER
OF TRAIL

Corner again.

Give any further facts which will aid in finding this

chains distant.


131

from which this ~~corner~~ bears W.C. BEARS ST. E

side of COUNTY ROAD

tree 8 inches diameter, on the W.E.

Metal Location Poster is on a FENCE POST



(Make sketch of topography near Corner)

T. 150N R. 27W S Mer. P-21