

U. S. Department of Agriculture

FOREST SERVICE

9

Chippewa NATIONAL FOREST G-21

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 27 5 Mer.

1/4 Corner common to Sections 11, and 12

Corner consists of a Post (not) in place

State condition marked 1/4 S-11

Dimensions above ground H. 28" Dia. 3"x3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

L. Th. Johnson

(Signature)

Surveyor

(Title)

2-1-38

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

~~tree inches diameter, on the East of corner~~

5x4x5

Metal Location Poster is on a Cedar Post



(Make sketch of topography near Corner)

T. 150 R. 27 S. Mer.

6-21

G-21

Post


Section Corners

1/4 11-12

150

27

5



Section 10

Post

28"

3" x 3"

11-5

1/4 5-12

Section 10

Date

Speaker

Weather

Reading

Remarks

Total points

Pedar Post East of

Location

1/4 Cor. 54 LK5

2-1-34

Floyd W. Johnson

G-21

