

E1

U. S. Department of Agriculture

FOREST SERVICE

posted

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 28 S. 5 Mer.

Corner common to Sections

1 (150-29), 12 (150-29), 16, and 7 (150-29)

Corner consists of a Spruce stake (net) in place

State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

T150N	S	S	6
R29W	12	7	6
S1			

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			S 6
			BT

Species L Tammyak-End

Diameter 6

Bearing N35°W

Distance 50 L

Do you believe this to be a genuine Land Office Corner? No

If not, why? Markings were too fresh.

Lloyd M. Peter

(Signature)

Dec. 21, '33

(Date)


Estimator

(Title)

E-1

Corner again.
 The survey lines
 are cut out and are
 fairly plain.
 There are several lines
 (MS) cut out the more
 westerly line is the line
 on which the corner
 stake is located

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a *map post*



(Make sketch of topography near Corner)