

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 150 N R. 28 W 5th Mer.  
149 N  $\frac{1}{4}$  Corner common to Sections  
 -----, -----, 2, and 35

Corner consists of a Balsam Stake (not) in place  
 State condition Rotted off at bottom

Dimensions above ground 3" X 3" X 30" inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

$\frac{1}{4}$ 5 35		$\frac{1}{4}$ 5 2	
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species -----

Diameter -----

Bearing None -----

Distance -----

Do you believe this to be a genuine Land Office Corner? 3

If not, why? -----

Field Man: Harvie (H. Norman)  
 (Signature)


Sept. 26, 1935  
 (Date)

LEM. (IF)  
 (Title)

2-19

Corner again.  
Corner has Virgin Timber on  
South side and second growth  
on East side. Stake is  
among three pcs. of logs

Give any further facts which will aid in finding this  
chains distant.  
0.27  
from which this Corner bears 524° W  
side of Tree  
tree 9 inches diameter, on the SW  
Metal Location Poster is on a 13x4



(Make sketch of topography near Corner)

T. 150 N. R. 20 W. 5th Mer. 199 W

219

U. S. Department of Agriculture

FOREST SERVICE

Posted

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150N R. 28W 5th Mer.

Quarter Corner common to Sections

35

Corner consists of a Post (not) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		T150	
S		R28	
35		W	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

None found.			

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? Placed too recently

Ralph Hunt

(Signature)

Chief of party.

4/2/35

(Date)


(Title)

2-19

Lined writing area for notes.

Metal Location Poster is on a \_\_\_\_\_  
 tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_  
 side of \_\_\_\_\_  
 from which this Corner bears \_\_\_\_\_  
 chains distant.

Give any further facts which will aid in finding this  
 Corner again.



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

219  
*219*  
*Post*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 N R. 28 W 5th Mer.  
191 1/4

Corner common to Sections  
 \_\_\_\_\_, \_\_\_\_\_, 2, and 35

Corner consists of a Balsam Stake (~~not~~) in place  
 State condition rotted off at bottom.

Dimensions above ground 30" X 3" X 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/2</u> <u>35</u>		<u>1/2</u> <u>3</u> <u>2</u>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter None \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? ?

If not, why? \_\_\_\_\_

Field Man: Home (H. Norman)

(Signature)

Sept. 26, 1935  
 (Date)

LEM. (J.F.)  
 (Title)

Corner has Virgin Timber  
on South side and Second  
growth on East side. State  
is among 3 per. of logs

Corner again.

Give any further facts which will aid in finding this


0.27 chains distant.

from which this Corner bears S 29° W

side of line

tree 9 inches diameter, on the SW

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 150N R. 28W S. 24 Mer.

# U. S. Department of Agriculture

## FOREST SERVICE

NATIONAL FOREST

### CORNERS OF THE PUBLIC SURVEY

T. 150 N R. 28 W 5th P Mer.

14 1/4

Corner common to Sections

2, 35, and

Corner consists of a Balsam Stake in place

State condition rotted off at bottom

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>		<u>1/4</u>	
<u>S</u>		<u>S</u>	
<u>35</u>		<u>2</u>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing N 30 E \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

Field Man: Home (N. Morrison)

(Signature)

(J.F.)

(Date)

(Title)

Corner has Virgin the last  
on South side and second  
plot on East side. Slope is  
slight 2 pieces of logs.

Corner again.

Give any further facts which will aid in finding this


27 links ~~is~~ distant.

from which this Corner bears  
S 24° 15' W

side of ~~the~~

tree 9 inches diameter, on the SW

Metal Location Poster is on a Birch



149 N (Make sketch of topography near Corner)

T. 149 N R. 28 W Mer.



U. S. Department of Agriculture

FOREST SERVICE

NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 150 N R. 23 W 5TH Mer.

14 Corner common to Sections

35, and

Corner consists of a Post (not) in place

State condition Good

Dimensions above ground 50 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	E	E
150		23	
		Post	
		W	

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Too Recent

Ralph \_\_\_\_\_

(Signature)

Chief of Party

(Title)

4/2/25

(Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


----- chains distant.

----- from which this Corner bears

----- side of

----- tree ----- inches diameter, on the

----- Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

111

R. B. W.

T. 150N