

U. S. Department of Agriculture

FOREST SERVICE

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150N R. 28W 5 Mer.

4 Corner common to Sections
13, and 18

Corner consists of a POST (not) in place
 State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

4 5 12	4 5 18		
B.T.	B.T.		

Species ASPEN ASPEN

Diameter 5" 8"

Bearing S 88° E N. 55° W

Distance .08 .09

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

LLOYD W. JOHNSON
 (Signature)

SURVEYOR
 (Title)

2-13-24
 (Date)

L-25

CENTER OF OLD ROAD
1.09 CHS. SOUTH OF Y COR.
13-18

CORNER AT N.E. CORNER
OF OLD CLEARING

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree 5" inches diameter, on the S 48° E - 08
S 26° W - 13 1/2

Metal Location Poster is on ASPEN



(Make sketch of topography near Corner)

T. 150N R. 28W S Mer.