

T 57N R 27W M 4th

T \_\_\_\_\_ R \_\_\_\_\_ M \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_ M \_\_\_\_\_

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
C	+	6	+	+	5	+	+	4	+	+	3	+	+	2	+	+	1	+	+	+	+	+	+	+	+
D	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
E	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
F	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
G	+	7	+	+	8	+	+	9	+	+	10	+	+	11	+	+	12	+	+	+	+	+	+	+	+
H	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
J	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
K	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
L	+	18	+	+	17	+	+	16	+	+	15	+	+	14	+	+	13	+	+	+	+	+	+	+	+
M	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
N	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
O	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
P	+	19	+	+	20	+	+	21	+	+	22	+	+	23	+	+	24	+	+	+	+	+	+	+	+
Q	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
R	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
S	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
T	+	30	+	+	29	+	+	28	+	+	27	+	+	26	+	+	25	+	+	+	+	+	+	+	+
U	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
V	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
W	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
X	+	31	+	+	32	+	+	33	+	+	34	+	+	35	+	+	36	+	+	+	+	+	+	+	+
Y	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+

LEGEND

○ = Corner having information on form 7100-52 in this file.

T57N R27W 4th PM


FILING INSTRUCTION

(Ref. FSM 7150)

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.



Index No. E-25  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RR-7150-4 (Rev. 6/13/67)  
 GPO 802-127

T. 57N R. 27W 4th Mer. N.F. CHIPPEWA County ITASCA State MINNESOTA  
NE SECTION Corner common to sections 12 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
 Original monument POST  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>ASH</u>	<u>W. CEDAR</u>	<u>W. CEDAR</u>	<u>ASH</u>
Diameter	<u>4"</u>	<u>8"</u>	<u>6"</u>	<u>11"</u>
Bearing	<u>N04W</u>	<u>N33E</u>	<u>S85E</u>	<u>S74W</u>
Distance	<u>27 links</u>	<u>24 links</u>	<u>19 links</u>	<u>36 links</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Where filed or recorded \_\_\_\_\_  
 Monument 2" O.D. IRON PIPE W  
3" DIA. BRASS CAP STAMPED:

T57N  
 116  
 127  
 1976  
 R27W  
 R27E

Bearing Trees, Reference Objects


Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_



Sketch

Corner  F.S. Land

Relation of Evidence to Record Features Along Section Lines

E-25

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?  Yes  No

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search 1/4

4. Do you think additional search might recover evidence? Yes  No


OFF STN, 1/4 W 3/4 P. 4 Perpetuation Record GRANN 8/82

Monument and accessories established. Include brief description of area. \_\_\_\_\_

RECORDED 1/4 1/4 1.4' ABOVE 'ROUND' CORNER 4" X 3" WOOD

LOST SCRIBED:

SCRIBING BARREL



NO EVIDENCE VIGORUE

ACCESSORIES:

ELM 6" S24W, 10.45', SCRIBING  
 ASH 1/4" N80W, 19.50', SCRIBING  
 ASH 2" N20W, 35.28', SCRIBING  
 1/4" SIGN POST, 3.31', 1/4" 4.54'

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

5. Signature Alan P. Kovando

T. 52N R. 22W 4 Mer. N.F. Chippewa County Itasca State Minnesota  
Township Corner common to sections 1 & 12 T52N, R22W and 6 & 9  
T52N R22W

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
 Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1938 By Forest Service  
 Where filed or recorded Marcell Ranger Station  
 Monument 1" Iron pipe - 9" cedar post  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>cedar</u>	<u>Ash</u>	<u>Ash</u>
Diameter	<u>12"</u>	<u>12"</u>	<u>18"</u>	<u>146"</u>
Bearing	<u>N33°E</u>	<u>S75°E</u>	<u>S94°W</u>	<u>N46°W</u>
Distance	<u>24 1/4</u>	<u>19 1/4</u>	<u>36 1/4</u>	<u>57 1/4</u>

Original Evidence Found


Year of search ~~1938~~ By D.S. Forest Service  
 Monument found tree stumps

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

At time of search:

1. Did you have the record description?

Yes YES No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
etc. chaining - photo

3. Man hours spent in search 3

4. Do you think additional search might  
recover evidence? Yes \_\_\_\_\_ No X

5. Signature J. P. Coyle

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
Object \_\_\_\_\_  
Record distance \_\_\_\_\_  
Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area.  
View. F.S. tag set. line blazed and pointed to south

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No NO

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. G-25  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57N R. 27W 4th Mer. N.F. SHIPPEWA County ITASCA State MINNESOTA  
1A Corner common to sections 12 7 and \_\_\_\_\_  
57-27 57-26

EXISTING SURVEYS

**Original Government Survey**

Year surveyed 213

Original monument 3"  
(Wood post, stone, pile of stones, pipe, etc.)

**Bearing Trees**

Species	<u>ASH</u>	<u>W. CEDAR</u>
Diameter	<u>10"</u>	<u>8"</u>
Bearing	<u>S21W</u>	<u>S87E</u>
Distance	<u>25 links</u>	<u>4 links</u>

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1924 By \_\_\_\_\_

Where filed or recorded \_\_\_\_\_

Monument 1" IRON PIPE AND 4" BALSAM POST  
(Original, concrete post, iron rod, etc.)

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By FORNHAM, POWERS, BIRD  
RECOVERED COUNTY MONUMENT IN ASH SWALE

**Bearing Trees, Reference Objects**


Species	<u>ASH</u>	_____
Diameter	<u>8"</u>	_____
Bearing	<u>S63W</u>	_____
Distance	<u>8 links</u>	_____

**Bearing Trees, Reference Objects**

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

6-25

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner  F.S. Land

Section line to sections \_\_\_\_\_

Object \_\_\_\_\_

Record distance \_\_\_\_\_

Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes  No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search 1/4

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No

5. Signature Blond P. Kautz

SEE T57N N, BK. 8G. Perpetuation Record 20

Monument and accessories established. Include brief description of area.

RECOVERED 1/2" O.D. IRON PIPE W. 2 FT. DIA. ALUMINUM CAP STAMPED:

ASSIGNMENTS: ELM, 9" S59E, 25.27', SCRIBING

ELM, 14" S14E, 22.87', SCRIBING

ASH, 12" N12W, 31.48', SCRIBING


ROCK W/ "X" VISIBLE; 2ND ROCK W/ "X" VISIBLE

ELM, 8" S11E, 50.58', SCRIBING, 60d SACK

METAL FENCE POST, S02W, 2.95', W/ 54-9, 54-2

METAL FENCE POST, NOZE, 4.34', W/ 54-2

60d SACK



Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

F.P.E. 103 4 1:11



INDEX No. G-25  
(Alphabetical Numbering)


LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57 R. 27 4th M.R. N.F. CHIPPewa County ITaska State MIN  
1/4 Corner common to sections 12 7 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;">Subsequent Corner Restoration</p> Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small> <u>SEE BOOK 1 PAGE 3</u>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p> Year of search _____ By _____ _____ _____ _____
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Bearing Trees, Reference Objects</p> _____ _____ _____ _____



Sketch

O Corner  F.S. Lead

At time of search:

1. Did you have the record description?  
Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
Pacing, chaining, photos, maps,  
etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature B. AUSK

Section line to sections \_\_\_\_\_  
Object \_\_\_\_\_  
Record distance \_\_\_\_\_  
Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

RECOVERED a 1 1/2" IRON PIPE w/ 1/2" ALUMINUM CAP STAMPED.


Elm 9" S59°E 25.27'

Elm 14" S14°E 22.87'

Ash 12" N120°W 31.48'

Rock 1x2' N72°W 60.25'

Rock 2'x2' N33°W 64.93'



G. KOSENKO

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. J-21  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
Section \_\_\_\_\_ Corner common to sections 11, 12, 13 and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 F. G. Winston

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species W. Birch W. Ash Elm B.O.G.  
Diameter 15" 10" 10" 9  
Bearing S17°-30'W S64°W N62°-15'E N23°-45'W  
Distance 15 lks 52 lks 4 lks 15 lks

Subsequent Corner Restoration

Year surveyed 1935 By L. W. Johnson

Where filed or recorded Itasca Co.

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Cedar Stp W. Ash \_\_\_\_\_  
Diameter 18" 15" \_\_\_\_\_  
Bearing N46°E S25°E \_\_\_\_\_  
Distance 25.9' 37.0' \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Itasca County perpetuated this corner in 1964 and 1976 and 1985 and 1987.

5/23/94 R. MAIN + C. KRAUSE

NO USES MONUMENT COULD BE LOCATED

1" X 1" X 20" LONG IRON PIN WAS FOUND AT TRUE CORNER LOCATION

B.T. OK

At time of search:

1. Did you have the record description?  
 Yes X No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Intersection of roads

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No X

5. Signature John J. Higgins

Perpetuation Record

Monument and accessories established. Include brief description of area. Set  
2" pipe 18" long w/magnetic breakaway base in intersection  
of roads, new B.T. as follows:

Aspen	Ash	Ash
5"	7"	5"
N6°W	N32°E	S23°E
25.65'	52.32'	100.60'

Certified corner restoration certificate prepared: Yes X No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. 41451

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. J-21, 22  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
M.C. W. Shore Island Lake Corner common to sections 12, 13, and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 By F. G. Winston  
Original monument Post  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Cedar Birch  
Diameter 9" 8"  
Bearing N75°W S76°W  
Distance 35 lks 64 lks

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search 1989 By John Hinzmann  
Monument found None

Original Bearing Trees Found


Species None  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes  No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Next to NW Sec.  
Cor.

3. Man hours spent in search 4

4. Do you think additional search might

recover evidence? Yes \_\_\_\_\_ No

5. Signature John J. Hinzman

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

This corner was not set; the corner would fall in  
a boat landing (Public Access) only 30 feet east  
of the Section Corner.

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. J-22, 23  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
Meander Corner common to sections 12, 13, and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 F. G. Winston  
Original monument post  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Spruce Spruce  
Diameter 6" 9"  
Bearing N22°E S33°W  
Distance 29 lks 36 lks

Subsequent Corner Restoration

Year surveyed 1976 By Itasca Co.  
Where filed or recorded Itasca Co.  
Monument 2" diameter brass capped pipe  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Rock Rock Cedar  
Diameter 1x2½ 1½x2½ 7"  
Bearing N56°E S55°E S20°W  
Distance 43.06' 41.72' 8.89'

(tag only)

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes X No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Shore of Lake

West of 1/4 Cor.

3. Man hours spent in search 1

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No X

5. Signature John J. Henjima

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

In 1989 Itasca Co. monument was found and its  
 position accepted. Witnessed by:

<u>Birch</u>	<u>Cedar</u>	<u>Birch</u>
<u>16"</u>	<u>7" (12" now)</u>	<u>6"</u>
<u>N84°E</u>	<u>S20°E</u>	<u>S12°E</u>
<u>13.71'</u>	<u>8.89'</u>	<u>8.44'</u>

(1976 Itasca Co.) 9

Certified corner restoration certificate prepared: Yes X No \_\_\_\_\_

Filed in county records of \_\_\_\_\_ Date \_\_\_\_\_ County Document No. 411139

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. J-23  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
 GPO 502-127

T. 57 R. 27 4th Mer. N.F. CHIPPENAW County ITASCA State MN  
QUARTER Corner common to sections 12, 13 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
 Original monument WOOD POST  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species BASSWOOD MAPLE  
 Diameter 18" 12"  
 Bearing N24E S47W  
 Distance 84 lks 7 lks

Subsequent Corner Restoration

Year surveyed 1976 By ITASCA CO  
 Where filed or recorded \_\_\_\_\_  
 Monument 3/4" IRON PIPE IN E. OF ROAD.  
Co ROAD #140  
(Iron pipe, stone, post, iron rod, etc.)

Bearing Trees, Reference Objects

Species X ROCK P POLE OAK XON CONCRETE  
 Diameter 2 1/2 X 3 8" MAZIL BOX POST  
 Bearing N 81 E EAST S 33 W N 12 W  
 Distance 28.47 35.84 52.40 35.70

Original Evidence Found

Year of search 1919 By L.W JOHNSON  
 Monument found PLAT INDICATES GOVT CORNER

Original Bearing Trees Found


Species BASSWOOD MAPLE  
 Diameter 7" 9"  
 Bearing N 68 W N 66 E  
 Distance 45.1 43.1

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of oreo. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records of \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. J-24  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
East 1/16 Corner common to sections 12, 13, and \_\_\_\_\_

EXISTING SURVEYS

**Original Government Survey**

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

**Bearing Trees**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Where filed or recorded \_\_\_\_\_

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Bearing Trees, Reference Objects**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_


**Bearing Trees, Reference Objects**

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature

*John J. Arizma*

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Corner is a 48" long 2" diameter brass capped pipe with witness as follows:

Spruce	Birch	Birch
18"	6"	8"
N65°W	N48°E	S31°E
29.68'	23.86'	17.25'

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No X

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_


Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

T. 57N R. 27W 4th P Mer. N.F. Chippewa County Itasca State Minnesota  
Section Corner common to sections 12, 13, 7 and 18  
T57N R27W T57N, R26W

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;"><b>Bearing Trees</b></p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;"><b>Original Bearing Trees Found</b></p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;"><b>Subsequent Corner Restoration</b></p> Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<p style="text-align: center;"><b>Evidence of Subsequent Corner Restoration Found</b></p> Year of search _____ By _____ _____ _____ _____ _____ _____ _____
<p style="text-align: center;"><b>Bearing Trees, Reference Objects</b></p> Species _____ Diameter _____ Bearing _____ Distance _____	_____ _____ _____ _____

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner    ▨ F.S. Land

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. F. S. tag on corner tree.

Blazed and painted line runs West from this corner. No brass cap found (4/65)

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No X

2. How was search area located?

Pacing, chaining, photos, maps, etc. chaining, photo

3. Man hours spent in search 2

4. Do you think additional search might recover evidence? Yes X No \_\_\_\_\_

5. Signature F. L. Coyle

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. J-25  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7 150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57 R. 27-26 4TH Mer. N.F. CHIPPEWA County ITASCA State MN  
SECTION Corner common to sections 7, 12, 13 and 18

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument WOOD POST  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>WCEDAR</u>	<u>WCEDAR</u>	<u>WCEDAR</u>	<u>ASH</u>
Diameter	<u>10</u>	<u>12</u>	<u>12</u>	<u>10</u>
Bearing	<u>N16W</u>	<u>N56E</u>	<u>S53E</u>	<u>S27W</u>
Distance	<u>6 lks</u>	<u>30 lks</u>	<u>18 lks</u>	<u>13 lks</u>

Original Evidence Found

Year of search 1919 By L.W. JOHNSON  
Monument found ORIGINAL

Original Bearing Trees Found

Species	<u>BALSAM</u>	<u>BALSAM</u>	<u>CEDAR</u>	<u>CEDAR</u>
Diameter	<u>7"</u>	<u>8"</u>	<u>10"</u>	<u>6"</u>
Bearing	<u>N70E</u>	<u>S45E</u>	<u>S17W</u>	<u>N53W</u>
Distance	<u>50.9</u>	<u>45.0</u>	<u>47.7</u>	<u>49.9</u>

Subsequent Corner Restoration

Year surveyed 1929 By P.C. WARNER  
Where filed or recorded ITASCA CO PLAT  
Monument IRON PIPE  
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search 1958 By F.L. COYLE U.S.F.S.  
SET A SQUARED CEDAR POST FOR CORNER.  
FD ONE ORIGINAL CEDAR BT.

Bearing Trees, Reference Objects

Species	<u>BALSAM</u>	<u>BALSAM</u>	<u>CEDAR</u>	<u>CEDAR</u>
Diameter	<u>7"</u>	<u>8"</u>	<u>10"</u>	<u>6"</u>
Bearing	<u>N70E</u>	<u>S45E</u>	<u>S17W</u>	<u>N53W</u>
Distance	<u>50.9</u>	<u>45.0</u>	<u>47.7</u>	<u>49.9</u>

Bearing Trees, Reference Objects

<u>CEDAR</u>			
<u>14"</u>			
<u>S24W</u>			
<u>78 lks</u>			



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_

Object \_\_\_\_\_

Record distance \_\_\_\_\_

Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records of \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. J-25  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
 GPO 802-127

T. 57 R. 27-26 4TH Mer. N.F. CHIPPewa County ITASCA State MN  
SECTION Corner common to sections 7, 12, 13 and 18

EXISTING SURVEYS

Original Government Survey

Year surveyed 1976 ITASCA CO  
 Original monument Ed 1" IRON ROD IN SWAMP. REPLACED  
(Wood post, stone, pile of stones, pipe, etc.)  
WITH COUNTY MONUMENT

Bearing Trees

Species	Ash	Ash	Ash	CEDAR
Diameter	6"	14"	14"	12"
Bearing	N45E	S87E	S58W	S28E
Distance	27.82	7.18	13.34	36.74

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1982 By G. KOSENKO USFS.  
 Where filed or recorded \_\_\_\_\_  
 Monument Ed COUNTY MONUMENT WITH CAP  
(Original concrete post, iron rod, etc.)  
BROKEN OFF. REPLACED WITH 3 1/2" X 5' GALVANIZED  
STEEL PIPE WITH 3" BRASS CAP. NEW MONUMENT  
ALONG SIDE COUNTY IRON.

Bearing Trees, Reference Objects


Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

MONUMENT STAMPED; T57N R27W  
 S12/S7  
 S13/S18  
 1983  
 RLS 14677

STEEL SIGN POST 2.95 FT NORTH

Certified corner restoration certificate prepared: Yes  No \_\_\_\_\_

Filed in county records at ITASCA Date \_\_\_\_\_ County Document No. 363216

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. J-25  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7160-4 (Rev. 6/13/67)  
 GPO 802-127

T. 57 N R. 27 W 4<sup>th</sup> Mer. N.F. Chippewa County Itasca State Minnesota  
Section Corner common to sections 12, 13, 7 and 18  
57-27 57-27 57-26 57-26

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
 Original monument post  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>W. Cedar</u>	<u>W. Cedar</u>	<u>W. Cedar</u>	<u>Ash</u>
Diameter	<u>10 in</u>	<u>12 in</u>	<u>12 in</u>	<u>10 in</u>
Bearing	<u>N16°W</u>	<u>N56°E</u>	<u>S53°E</u>	<u>S27°W</u>
Distance	<u>6 lks</u>	<u>30 lks</u>	<u>18 lks</u>	<u>13 lks</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1958 By F.L. Coyle  
 Where filed or recorded \_\_\_\_\_  
 Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search 1976 By County survey crew  
Found 1 in iron rod down in swamp  
Replaced w/ a county monument

Bearing Trees, Reference Objects

Species Cedar  
 Diameter 14 in  
 Bearing S24°W  
 Distance 70 lks

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_



Sketch

○ Corner  F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_

Object \_\_\_\_\_

Record distance \_\_\_\_\_

Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes  No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search 1/4

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No

5. Signature Alvin P. Kozanbo

See: T57N E27W BK1 pg 2 Perpetuation Record

Monument and accessories established. Include brief description of area. 8/82

Recovered 2" D.D. I.P. w/remains of aluminum cap attached.

Cap Broken off. Monument 1.1 ft above swamp

Accessories: Ash, 6", N54°E, 28.05 ft

<u>Ash, 14", S81°E, 7.50 ft</u>	<u>Cedar, 12", N16°W, 24.65'</u>
<u>Cedar, 14", S17°E, 37.08 ft</u>	<u>W. Cedar, N57°E, 19.92'</u>
<u>Ash, 14", S64°W, 13.70 ft</u>	<u>W. Cedar, S57°E, 11.60'</u>
<u>Cedar, 7", N46°W, 50.42</u>	<u>W. Cedar, N06°W, 5.10'</u>

Steel sign post, N02°E, 2.95' w/54-2,54.9

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. J, K-21  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 502-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
Property \_\_\_\_\_ Corner common to sections 13, 14, \_\_\_\_\_ and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

O Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature

*John J. Henington*

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_  
 Corner is in centerline of road and is a 18" long  
 2" diameter brass capped pipe with magnetic breakaway  
 base and witness as follows: \_\_\_\_\_

S.W. Cor. House	Balsam	Spruce
	18"	19"
N58°E	S64°W	N53°W
69.91'	37.92'	41.91'

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. J, K-21, 22  
(Alphabetical - Numerical)


LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7 150-4 (Rev. 6/15/67)  
 GPO 802-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
 Property Corner common to sections 13 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;">Subsequent Corner Restoration</p> Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p> Year of search _____ By _____ _____ _____ _____
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Bearing Trees, Reference Objects</p> _____ _____ _____ _____



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature *John J. Hinzman*

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Corner is on shore of Island Lake and is a 48" long  
2" diameter brass capped pipe with witness as  
follows:

Ash	Ash
10"	13"
S40°W	S3°E
14.90'	15.44'


Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_







Sketch

○ Corner    ▨ F.S. Land  
 XXX Fences

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. *No corner evidence found. App. corner is probably at a near fence corner. A blue line runs W + S from the vicinity, but the location of this line is questionable (10-20/65)*

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No

2. How was search area located?

Pacing, chaining, photos, maps, etc. *pacing + compass*

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes  No \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

5. Signature G. R. Jaboke

Index No. K-22, 23  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)  
GPO 802-127T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
SMC Corner common to sections 13 and \_\_\_\_\_

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

## Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

## Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might

recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature *John J. Arizima*

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Corner is on shore of Island Lake and is a 48" long  
2" diameter brass capped pipe with witness as  
follows:

Basswood	Balsam	Ash
14"	6"	12"
N60°E	S59°E	S5°W
6.91'	17.94'	5.51'

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. K-23  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/13/67)  
GPO 502-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
Center - North 1/16 Corner common to sections 13 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature John J. Hryman

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Corner is a 18" long 2" diameter brass capped pipe  
in the centerline of the road with witness as  
follows:

Basswood	Maple	Basswood
20"	11"	8"
S66°E	S32°W	N76°W
88.34'	42.74'	26.88'

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No X

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. K-24  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RR-7 150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57N R. 27W Mer. N.F. 4th Chippewa County Itasca State MN

Corner common to sections \_\_\_\_\_, \_\_\_\_\_ and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description? Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located? Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Corner is a 48" long 2" diameter brass capped pipe with witness as follows:

Basswood	Basswood	Basswood
7"	11"	11"
N44°W	S59°E	S19°W
7.12'	10.34'	18.65'

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No X

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

5. Signature John J. Brynma Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. K-25  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
North 1/16 Corner common to sections 13, 18, and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1929 By P. C. Warner  
Where filed or recorded Itasca County  
Monument Iron pipe  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Cedar Maple  
Diameter 7" 12"  
Bearing N55°E S65°W  
Distance 14.8' 29.1'

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature

*John J. Skrymgeour*

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_  
Corner replaces P. C. Warner 1929 pipe with 48" long 2" diameter brass capped pipe and witness as follows:

Cedar	Cedar	Cedar
12"	15"	8"
N20°E	N61°E	S56°W
19.49'	14.98'	25.23'

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No X

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. K, L-25  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7 150-4 (Rev. 6/13/67)  
GPO 502-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
Meander Corner common to sections 13, 18, and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873 E. W. Griffin  
Original monument Post  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Tam Tam  
Diameter 6" 8"  
Bearing N44°W East  
Distance 18 lks 12 lks

Subsequent Corner Restoration

Year surveyed 1929 By P. C. Warner  
Where filed or recorded Itasca Co.  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Spruce Spruce  
Diameter 8" 6"  
Bearing S86°W N55°E  
Distance 14.4' 7.5'

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes X No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Control traverse

3. Man hours spent in search 9

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No X

5. Signature John J. Higgins

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Corner was established by P. C. Warner plat of 1929.  
Corner is 48" long 2" diameter brass capped pipe  
supported by 3 8' iron fence posts with witness as  
follows:

Ash	Spruce	Tam
6"	14"	6"
N36°E	N85°E	S57°W
43.34'	96.88'	42.40'

Certified corner restoration certificate prepared: Yes X No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. 41137

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. L-21  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)  
GPO 502-127T. 57 R. 27 4th Mer. N.F. CHIPPewa County ITASCA State MN  
QUARTER Corner common to sections 13 14 and \_\_\_\_\_

## EXISTING SURVEYS

## Original Government Survey

Year surveyed 1874  
Original monument WOOD POST  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species TAMARACK TAMARACK  
Diameter 10 12  
Bearing S35E S54 1/2 W  
Distance 10 lks 22 lks

## Subsequent Corner Restoration

Year surveyed. 1976 By ITASCA CO  
Where filed or recorded \_\_\_\_\_  
Monument SET 1/2" IRON PIPE  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species PALE X MARKED END X SOUTH  
Diameter \_\_\_\_\_ CUBERT END (CUBERT)  
Bearing S51W N67E S62E  
Distance 53.63 43.15 45.47

## Original Evidence Found

Year of search 1919 By Johnson  
Monument found \_\_\_\_\_

## Original Bearing Trees Found


Species oak FRANK POST  
Diameter 10"  
Bearing S40E S83W  
Distance 78.3 31.9

## Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

## Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. L-21  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)R9-7 150-4 (Rev. 6/13/67)  
GPO 802-127T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
Quarter Corner common to sections 13, 14, and \_\_\_\_\_

## EXISTING SURVEYS

## Original Government Survey

Year surveyed 1874 By F. G. WinstonOriginal monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species Tam Tam  
Diameter 10" 12"  
Bearing S35°E S54°-30'W  
Distance 10 lks 27 lks

## Subsequent Corner Restoration

Year surveyed 1934 By L. W. Johnson

Where filed or recorded \_\_\_\_\_

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species Oak Fen. Post  
Diameter 10"  
Bearing S40°E S83°W  
Distance 78.3' 31.9'

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

## Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

## Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_



Sketch

O Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections: \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_  
Itasca County set and witnessed a 1/2" I.P. in 1976.

At time of search:

1. Did you have the record description?

Yes X No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Road intersections

3. Man hours spent in search 1

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No X

5. Signature John J. Kingma

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_  
Corner is 18" long 2" diameter brass capped pipe 6" below road surface with magnetic breakaway base and witness as follows:

<u>P. Pole</u>	<u>Oak</u>
	<u>10"</u>
<u>S55°W</u>	<u>S47°E</u>
<u>53.63'</u>	<u>101.53'</u>

Certified corner restoration certificate prepared: Yes X No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. 41136

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. L-24,25  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)  
 GPO 802-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
 Witness to Quarter Corner common to sections 13, 18, and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed Not set original  
 Original monument 1919 L. W. Johnson  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species W. Pine Birch  
 Diameter 14" 13"  
 Bearing S85°E N25°E  
 Distance 2.00' 6.4'

Subsequent Corner Restoration

Year surveyed 1929 By P. C. Warner  
 Where filed or recorded Itasca Co.  
 Monument Iron monument in pine stump  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Maple W. Pine  
 Diameter 10" 11"  
 Bearing S75°W N8°W  
 Distance 11.3' 10.0'

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_


Evidence of Subsequent Corner Restoration Found

Year of search 1987 By B. Ausk  
D. Ojanen (U.S.F.S.)

1989 By J. Hinzmann, Jr.  
H. Madison, B. Jukich

Bearing Trees, Reference Objects

Maple Snag Pine stump in lake  
Now 16" record brg. & dist.  
S75°W from maple  
11.3'



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes X No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Control traverse,  
road survey notes

3. Man hours spent in search 17

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No X

5. Signature John J. Higgins

Perpetuation Record

Monument and accessories established. Include brief description of area. Corner is 48" long 2" diameter brass capped pipe with witness as follows:

Maple	Maple	Maple	Maple Snag
8"	6"	12"	16"
N57°W	S55°W	S18°W	S40°E
33.21'	49.30'	21.09'	4.41'

Corner was set on line 12.5' west of orig. position

Certified corner restoration certificate prepared: Yes X No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. 41135

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. L, M-25  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7 150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
Meander Corner common to sections 13 18 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873 E. W. Griffin  
Original monument Spruce tree  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Tam Elm  
Diameter 8" 6"  
Bearing West S50°E  
Distance 13 lks 7 lks

Subsequent Corner Restoration

Year surveyed 1929 By P. C. Warner  
Where filed or recorded Itasca Co.  
Monument Iron pipe  
(Original, concrete post, pipe, etc.)

Bearing Trees, Reference Objects

Species Govt. Tam Govt. Elm  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

Found iron pipe, but no witnesses.

At time of search:

1. Did you have the record description?

Yes X No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Control traverse

3. Man hours spent in search 4

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No X

5. Signature John D. Arizona

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Corner is 48" long 2" diameter brass capped pipe  
 with witness as follows:

Ash	Birch	Balsam
4"	12"	12"
S62°E	S13°E	S12°W
11.06'	21.18'	52.11'

Certified corner restoration certificate prepared: Yes X No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. 411134

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. N-1  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)

GPO 802-127

T. 57 N R. 26 to 27 4<sup>th</sup> Mer. N.F. Chippewa County Hasca State Mo  
SECTION Corner common to sections 13, 18, 19 and 24

## EXISTING SURVEYS

## Original Government Survey

Year surveyed 1874  
Original monument WOOD POST  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species	<u>LINDEN</u>	<u>W. BIRCH</u>	<u>P. PINE</u>	<u>SUGAR</u>
Diameter	<u>8"</u>	<u>12"</u>	<u>24"</u>	<u>10"</u>
Bearing	<u>N56E</u>	<u>N13E</u>	<u>S34E</u>	<u>S50W</u>
Distance	<u>34 lks</u>	<u>38 lks</u>	<u>37 lks</u>	<u>15 lks</u>

## Subsequent Corner Restoration

Year surveyed 1964 By Hasca County  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species	<u>T.P.</u>	<u>P.P.</u>	<u>Elm</u>	<u>W.C.</u>
Diameter			<u>3"</u>	
Bearing	<u>N60°E</u>	<u>S60°W</u>	<u>South</u>	<u>North</u>
Distance	<u>68.15'</u>	<u>62.95'</u>	<u>65.57'</u>	<u>33.0'</u>

## Original Evidence Found

Year of search 1929 By PLAT BY P.C. WARNER  
Monument found SET IRON. Fd 4 GOVT B.T.s

## Bearing Trees Found


Species	<u>BIRCH</u>	<u>BIRCH</u>	<u>1-WOOD</u>
Diameter	<u>16"</u>	<u>16"</u>	<u>8"</u>
Bearing	<u>N12E</u>	<u>S44°15'E</u>	<u>S67°45'W</u>
Distance	<u>25.0</u>	<u>56.0</u>	<u>18.6</u>

## Evidence of Subsequent Corner Restoration Found

Year of search 1981 By Hasca County  
Monument in road bed from which:  
64 PP, S60°W, 62.95'  
64 Elm, 3" South, 65.57'  
64 Mon., North, 33.0'

## New BT's Bearing Trees, Reference Objects

New BT's	Bearing Trees, Reference Objects	
<u>X-rock</u>	<u>X-rock</u>	<u>X-rock</u>
<u>2'x2'</u>	<u>1½'x2'</u>	<u>1½'x2'</u>
<u>N38°W</u>	<u>S43°W</u>	<u>S16°E</u>
<u>29.63'</u>	<u>34.62'</u>	<u>54.39'</u>



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. 5-6-85  
Robertson & Ausk Found 1 1/2 in. Iron Pipe 5 in.  
below road surface All BT's OK

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. N 21  
(Alphabetical - Numerical)


LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/84)

T. 57 N R. 27 W 4<sup>th</sup> P Mer. N.F. Chippewa County Stasca State Minnesota  
Section Corner common to sections 13, 14, 23 and 24

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small> <p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	Year of search _____ By _____ _____ _____ _____ _____ _____



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. *A recently set county brown-cap, located on the W side of FTR #2149. (10-21-65)*

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No X

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search 0

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No X

5. Signature G.R. Jaluka

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. N-21  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS) 1

R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57N R. 27W Mer. N.F. Chippewa County Itasca State MN  
Section \_\_\_\_\_ Corner common to sections 13, 14, 23 and 24

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 F. G. Winston

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	W. Pine	Spruce	Poplar	Fir
Diameter	<u>10"</u>	<u>6"</u>	<u>12"</u>	<u>8"</u>
Bearing	<u>N15°-30'E</u>	<u>N34°-30'W</u>	<u>S64°W</u>	<u>S73°E</u>
Distance	<u>63 lks</u>	<u>81 lks</u>	<u>48 lks</u>	<u>11 lks</u>

Subsequent Corner Restoration

Year surveyed 1919/1921 By L. W. Johnson/

Where filed or recorded K. K. Russell

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	N. Pine	Elm
Diameter	<u>9"</u>	<u>10"</u>
Bearing	<u>S71°W</u>	<u>S4½°W</u>
Distance	<u>166.8'</u>	<u>189.5'</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found


Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Itasca Co. perpetuated this corner in 1964 and 1976.

At time of search:

1. Did you have the record description?  
 Yes X No \_\_\_\_\_

2. How was search area located?  
 Pacing, chaining, photos, maps, etc. Intersection of roads

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No X

Perpetuation Record

Monument and accessories established. Include brief description of area. Corner is 18" long 2" diameter brass capped pipe with breakaway magnetic base and witness as follows:

Aspen	Aspen	P. Pole	P. Pole
8"	6"		
N67°W	N55°E	S62°E	S47°W
55.74'	127.21'	68.25'	45.95'

Certified corner restoration certificate prepared: Yes X No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. 411133

5. Signature John J. Henzler Identified on aerial photo No. \_\_\_\_\_ Which is filed of \_\_\_\_\_

Index No. N-21  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/15/67)  
GPO 802-127

T. 57 R. 27 4TH Mer. N.F. CHIPPEWA County ITASCA State MINN  
SECTION Corner common to sections 13 14 23 and 24

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument WOOD POST  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species W PINE SPRUCE ASPEN FIR  
Diameter 10" 6" 12" 8  
Bearing N15 1/2 E N34 1/2 W S64 W S78 E  
Distance 63 lks 81 lks 48 lks 11 lks

Original Evidence Found

Year of search 1919 By L.W. JOHNSON  
Monument found FOUND GOVT BT'S

~~Original~~ Bearing Trees Found

Species R PINE E 1m  
Diameter 9" 10"  
Bearing S71 W S4 1/2 W  
Distance 166.8 189.5

Subsequent Corner Restoration

Year surveyed 1940 By A.L. JOHNSON  
Where filed or recorded 874-9  
Monument Ed 3" SQUARED POST. NOT ORIGINAL  
Ed NO BT'S  
(Original, copy, cast, post, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search 1964 By ITASCA CO  
SET NEW SECTION CORNER FROM APPROXIMATE CORNER.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

P POLE P. POLE CO MONUMENT  
S44 W S60 E WEST  
45.96 67.98 45.00  
TO PK NAIL FLUSH



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Includes brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. N-23  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
Quarter Corner common to sections 13, 24, and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 F. G. Winston  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Aspen Aspen  
Diameter 5" 10"  
Bearing N27°E S66°E  
Distance 16 lks 24 lks

Subsequent Corner Restoration

Year surveyed 1919/1922 by L.W. Johnson/  
K.K. Russell  
Where filed or recorded Itasca Co.  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Poplar Elm  
Diameter 16" 12"  
Bearing S21°W N51°W  
Distance 77.9' 58.9'

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

Itasca Co. perpetuated this corner in 1964 with a 3/8" re-bar.

At time of search:

1. Did you have the record description?

Yes X No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. Control traverse

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No X

5. Signature John F. Arjona

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Corner is 18" long 2" diameter brass capped pipe with breakaway magnetic base and witness as follows:

Oak	N. Pine	Spruce	P.P.	Wit. Mon't.
16"	12"	10"		2" pipe
N5°W	N40°E	S40°E	S67°W	South
33.98'	81.21'	54.01'	84.88'	33.00'

(1964 Itasca Co.) (1981 Itasca Co.) (1964 Itasca Co.)

Certified corner restoration certificate prepared: Yes X No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. 411132

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. N-23  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)  
GPO 502-127T. 57 R. 27 4TH Mer. N.F. C HIPPEWA County ITASCA State MN  
QUARTER Corner common to sections 13 24 and \_\_\_\_\_

## EXISTING SURVEYS

## Original Government Survey

Year surveyed 1874  
Original monument WOOD POST  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees	
Species <u>ASPEN</u>	<u>ASPEN</u>
Diameter <u>5"</u>	<u>10"</u>
Bearing <u>N27E</u>	<u>S66E</u>
Distance <u>16</u>	<u>24</u>

## Subsequent Corner Restoration

Year surveyed 1964 By BENZING  
Where filed or recorded \_\_\_\_\_  
Monument SET NEW CORNER  
(Original, concrete post, wax rod, etc.)

## Bearing Trees, Reference Objects

Species <u>OAK</u>	<u>T POLE</u>	<u>CO IRON</u>
Diameter <u>7"</u>		
Bearing <u>N5W</u>	<u>N65E</u>	<u>SOUTH</u>
Distance <u>33.98</u>	<u>60.67'</u>	<u>33.00</u>

## Original Evidence Found

Year of search 1919 By L W JOHNSON  
Monument found NONE - SET NEW MONUMENT  
MEADPOINT ON LINE.~~Original~~ Bearing Trees Found


Species <u>ASPEN</u>	<u>ELM</u>
Diameter <u>16"</u>	<u>12"</u>
Bearing <u>S21W</u>	<u>N51W</u>
Distance <u>77.9'</u>	<u>59.1</u>

## Evidence of Subsequent Corner Restoration Found

Year of search 1981 By ITASCA CO  
ESTABLISH NEW BTS

## Bearing Trees, Reference Objects

<u>P.POLE</u>	<u>R PINE</u>	<u>SPRUCE</u>
	<u>6"</u>	<u>5"</u>
<u>S67W</u>	<u>N40E</u>	<u>S40E</u>
<u>84.88</u>	<u>81.21</u>	<u>54.01</u>



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might

recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

$\frac{3}{8}$ " REBAR 2' SOUTH OF CORN 160 & 2" below GRAVEL SURFACE.

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records of \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. N-25  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)  
 GPO 502-127

T. 57N R. 27W 4th Mer. N.F. Chippewa County Itasca State MN  
 Section \_\_\_\_\_ Corner common to sections 13, 18, 19 and 24

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873 - E. W. Griffin  
 Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>Linden</u>	<u>W. Birch</u>	<u>N. Pine</u>	<u>Sugar</u>
Diameter	<u>8"</u>	<u>12"</u>	<u>24"</u>	<u>10"</u>
Bearing	<u>N56°E</u>	<u>N13°E</u>	<u>S34°E</u>	<u>S50°W</u>
Distance	<u>34 lks</u>	<u>38 lks</u>	<u>37 lks</u>	<u>15 lks</u>

Subsequent Corner Restoration

Year surveyed 1929 By P. C. Warner  
 Where filed or recorded \_\_\_\_\_  
 Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Birch</u>	<u>I. Wood</u>
Diameter	<u>16"</u>	<u>16"</u>	<u>8"</u>
Bearing	<u>N12°E</u>	<u>S44-15E</u>	<u>S67-45W</u>
Distance	<u>25.0'</u>	<u>56.0'</u>	<u>13.6'</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found


Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

In 1929 P. C. Warner found a Govt. B.T.'s. Itasca Co. perpetuated this corner in 1964 and 1981.

At time of search:

1. Did you have the record description?

Yes X No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Control traverse

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No X

5. Signature John J. Hymine

Perpetuation Record

Monument and accessories established. Include brief description of area.  
Corner is 18" long 2" diameter brass capped pipe with breakaway magnetic base and witness as follows:

<u>2 Birch</u>	<u>Mont.</u>	<u>Ash</u>	<u>P.P.</u>
<u>12"</u>	<u>2" Co. Pipe</u>	<u>9"</u>	<u>-</u>
<u>N45°W</u>	<u>North</u>	<u>S12°E</u>	<u>S62°W</u>
<u>62.10'</u>	<u>33'</u>	<u>69.32'</u>	<u>62.95'</u>

Certified corner restoration certificate prepared: Yes X No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. 411452

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_