

LEGEND

○ = Corner having information on form 7100-52 in this file.

T60N R27W 4th PM


FILING INSTRUCTION

(Ref. FSM 7150)

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.



Index No. A-9 ?  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/13/67)  
GPO 802-127

S.L.

T. 60-61 R. R27W

4<sup>th</sup>

Mer. N.F. Chipewagon County Itasca

State Minnesota

Closing

Corner common to sections 4 & 34

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Minn. Hwy Dept.

Where filed or recorded \_\_\_\_\_

Monument 3/4" Iron Rod.  
(Original, concrete post, wood rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_


Evidence of Subsequent Corner Restoration Found

Year of search 1980 By R. Olesen

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner    ▨ F.S. Land

Section line to sections \_\_\_\_\_

Object \_\_\_\_\_

Record distance \_\_\_\_\_

Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?  
Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

from 1980 Itasca County resurvey.

Tol Pole S30E 93.39

X South End Culvert N57E 21.47'

X North End Culvert N17E 48.04'

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. A-13  
(Alphabetical - Numerical)

*Book #*

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

50.  
R9-7160-4 (Rev. 6/13/67)  
GPO 802-127

T. 60 N R. 27 W 4<sup>th</sup> Mer. N.F. Chippewa County Itasca State M. N. S. D.  
Clearing Section Corner common to sections 3 4 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Itasca County.  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_


Evidence of Subsequent Corner Restoration Found

Year of search 1980 By R. Olson

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner    ▨ F.S. Land

Section line to sections \_\_\_\_\_

Object \_\_\_\_\_

Record distance \_\_\_\_\_

Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

At time of search:

1. Did you have the record description?  
 Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
 Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area.

from 1980 Itasca County. to survey.

Old Balsam 13" S58W 18.91' from Nail

Old Poplar 13" S60E 35.94' " Nail

Balsam 6" N45W 18.72'

Poplar 7" N50E 15.54'

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. A-15  
(Alphabetical - Numerical)

*Boo #1*

*Page 30*

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7 150-4 (Rev. 6/15/67)

GPO 809-127

T. 60N R. 27W 4<sup>th</sup> Mer. N.F. Chippewa County Itasca State Minnesota  
Clearing 1/4 Corner common to sections 3 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
 Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Itasca County.  
 Where filed or recorded \_\_\_\_\_  
 Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search 1980 By R. Olson

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_



Sketch

○ Corner  F.S. Land

Relation of Evidence to Record Features Along Section Lines

A-15

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

At time of search:

1. Did you have the record description?  
 Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
 Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_  
 from 1980 Itasca County, Re-survey.  
 County Monument from which bears  
 old poplar 13" S 91 W 25.21 from Nail  
 old poplar 12" S 70 E 24.18 from Nail  
 spruce 5" S 30 W 52.09 from BT 52.38 from Nail  
 spruce 6" S 78 W 64.41  
 spruce 4" N 15 W 39.12

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_  
 Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. A-17  
(Alphabetical - Numerical)

*Book 81*  
*Page # 3*

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)

GPO 802-127

T. 60 N R. 27 W 4th Mer. N.F. Chippewa County Itasca State Minnesota  
Closing Section Corner common to sections 2 3

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stake, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Itasca County.

Where filed or recorded \_\_\_\_\_

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search 1980 By R. Olosen


Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

A-17

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?  
 Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
 Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

From 1980 Itasca County, Resurvey.  
 County Monument from which bears  
 Old Apler 12" S14W 19.90 from Nail  
 Old Basswood 12" S44E 22.63 " "  
 Birch 11" S14W 32.84 " "  
 Birch 6" S76E 8.70' from BT 9.21' from Nail  
 X Rock 15' x 2" N33E 21.36'  
 X Rock 24' x 3" S16W 29.49'  
 X Rock 1' x 1" West 8.77'

Certificate of corner restoration certificate provided. Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. A-19  
(Alphabetical - Numerical)

Plot #

#32

LAND CORNER RECORD

(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)

GPO 508-127

T. 60 N R. 27 W4<sup>th</sup>Mer. N.F. ChippewaCounty ItascaState MinnesotaClosing 1/4Corner common to sections 2

and \_\_\_\_\_

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Itasca County

Where filed or recorded \_\_\_\_\_

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

## Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_


Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Evidence of Subsequent Corner Restoration Found

Year of search 1980 By R. Oleson

## Bearing Trees, Reference Objects



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

A-19

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

*from 1980 Itasca County. Resurvey. County monument from which here*

*X Rock 1' x 1 1/2' S75W 9.84'*

*X Rock 2 1/2' x 3' S22E 27.38'*

*X Rock 3' x 4' N7E 92.40'*

*X Rock 2' x 2' N88E 53.50'*

*Balsam 8" South 25.36'*

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. A-20  
(Alphabetical-Numerical)

Book #1  
Page 3

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

510.  
R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 60 N. R. 27 W. 4th Mer. N.F. Chippewa County Itasca State Minnesota  
Closing Cor. Lot 1 & 2 Corner common to sections 2 and \_\_\_\_\_  
or East Closing 416

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1980 By Itasca County  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search 1980 By K. Oleson  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

A-20

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?  
 Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
 Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_  
*from 1980 County Reservey -  
 Set County Monument from which bears*

*Ash 4" S66W 20.37'  
 Ash 8" N33E 4.23'  
 Ash 8" N35W 3.50'*

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. A-21  
(Alphabetical-Numerical)

*Book #1*  
*age # 34*

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RS-7 150-4 (Ref. 6/13/67)

GPO 802-127

T. 60N R. 27W

*4<sup>th</sup>*

Mer. N.F.

Chippewa

County

Itasca

State

Minnesota

Closing 500

Corner common to sections 1 & 2

*501*

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_

(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_

By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_

By

Itasca County.

Where filed or recorded \_\_\_\_\_

Monument \_\_\_\_\_

(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search

1980

By

R. O. Logan

Bearing Trees, Reference Objects

Species \_\_\_\_\_


Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner    ▨ F.S. Land

Section line to sections \_\_\_\_\_

Object \_\_\_\_\_

Record distance \_\_\_\_\_

Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?  
Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
Pacing, chaining, photos, maps,  
etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

*from 1980 Itasca County, Resurvey.  
County Monument from which bears*

old Birch	6"	S12E	10.84
Ash	5"	S73W	7.92
Elm	8"	N44W	13.44
Cedar	14"	N21E	57.04

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. A-23  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

5.0.  
R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 60 N. R. 27 W. 4th Mer. N.F. Chippewa County Itasca State Minnesota  
Closing 1/4 Corner common to sections \_\_\_\_\_, \_\_\_\_\_ and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Itasca County.  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search 1980 By R. Olesen  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

A-23

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established, include brief description of area. \_\_\_\_\_

*from Resurvey 1980 by Ft. Sca County.*

*County Monument from which bears*

*Spruce 9" N55E 58.98*

*Spruce 11" N23W 37.35*

*Spruce 5" N57W 36.50*

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. A-25  
(Alphabetical - Numerical)

*Box - 1*

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 60 N. R. 27 W.  
Closing Sec

4th Mer. N.F. Chippewa County Itasca

State Minnesota

Corner common to sections 1 and 6

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Itasca County.  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search 1980 By R. Oleson  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

A-25

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

*Resurvey by Itasca County 1980*

*Barrow 9" S10W 153.84 from BT 153.73 from Nail  
 Elm 7" S75E 56.84 from BT 51.94 from Nail  
 x Rock 1' x 1 1/2' N30E 30.61'  
 x Rock 1' x 1 1/2' S28E 6.80'  
 8' Sign post East 1.78' & West 1.89'*

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_  
 Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. 5-13  
(Alphabetical - Numerical)

Ba

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7160-4 (Rev. 6/13/67)

GPO 802-127

5.0.

T. 60 N R. 27 W  
S. 14<sup>th</sup>

Mer. N.F.

Chippewa

County

Itasca

State

Minnesota

Corner common to sections

91015

and

16

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed 1961 By U.S. F.S.

Where filed or recorded \_\_\_\_\_

Monument 6" Concrete w/Brass Cap.  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species	Maple	Maple	Cedar Post	Cedar Post
Diameter	5"	4"	4x4	4x4
Bearing	N87E	S31E	S53W	N29W
Distance	37.42	7.15	2.6	3.6

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

## Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Evidence of Subsequent Corner Restoration Found


Year of search 1961 By R OlsonMonument in place and good Condition

Dead Down

## Bearing Trees, Reference Objects

Species	Maple	Cedar Post	Cedar Post
Diameter	7"	4x4	4x4
Bearing	N87E	S31E	S53W
Distance	37.42	7.15	2.6
			3.6

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner     F.S. Land

Section line to sections \_\_\_\_\_

Object \_\_\_\_\_

Record distance \_\_\_\_\_

Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

*Possible County. B&E*

*Basswood  
7"  
North  
35.3*

*Birch  
8"  
N60W  
10.5'*

*4/28/81  
Ronald Olson*

At time of search:

1. Did you have the record description?  
Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
Pacing, chaining, photos, maps,  
etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. J 15  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/81)

T. 60 N R. 27 W 4th Mer. N.F. Chippewa County Stasca State Miss.  
Quarter Corner common to sections 10 and 15

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Needle Monumentation  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found


Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner ~~to~~ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections -----  
 Object -----  
 Record distance -----  
 Measured distance -----

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

A county brasscap in the south ditch along  
 the Jingo Lake Road. Pipe tied to a W. Birch (w.  
 blue paint on it). 11-10-65

At time of search: .

1. Did you have the record description?

Yes \_\_\_\_\_ No X

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Accidental

3. Man hours spent in search 0

4. Do you think additional search might

recover evidence? Yes X No \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

5. Signature G. B. Jakobke



Index No. 121  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/81)

S.O.

T. 60N R. 27W 9<sup>th</sup> Mer. N.F. Chippewa County Stasca State Minnesota  
 Section Corner common to sections 11, 12, 13 and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
 Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Place in field Book  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration


Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Where filed or recorded \_\_\_\_\_  
 Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. *Lines brushed E-W, N-S. No corner evidence found. Blue line painted North a short distance. Needs a corner tag. (12/10/64)*

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No X

2. How was search area located?

Pacing, chaining, photos, maps, etc. *Photos, brushed line.*

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No X

5. Signature *G. Jakuba*

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. J-23  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RS-5660-11 (5/12/81)


T. 60N R. 27W 4th. P Mer. N.F. Chippewa County Itasca State Minnesota  
1/4 Corner common to sections 12 and 13

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____

Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By <u>Itasca County</u>	Year of search _____ By _____
Where filed or recorded <u>Itasca County Courthouse</u>	_____
Monument <u>2" iron pipe w/brass cap.</u> <small>(Original, concrete post, iron post, etc.)</small> <u>4" Cedar squared stake</u>	_____
_____	_____
_____	_____

Bearing Trees, Reference Objects		
Species <u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>
Diameter <u>10"</u>	<u>12"</u>	<u>10"</u>
Bearing <u>S77W</u>	<u>S66W</u>	<u>N39E</u>
Distance <u>19 lks.</u>	<u>12.07'</u>	<u>26 Lks</u>
	<u>17.42</u>	



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No

2. How was search area located?

Pacing, chaining, photos, maps, etc. Chaining - photo

3. Man hours spent in search 2

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No

5. Signature J. L. Coyle

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

County metal tag set on 12" Cedar tree on random line 134 feet south of corner. (Bakem)

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. L-13  
(Alphabetical - Numerical)Book #1  
Page #4LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)

GPO 802-127

5.0

T. T60N R. 27W4<sup>th</sup>

Mer. N.F.

Chippewa

County

Itasca

State

MinnesotaCorner common to sections 15 & 16

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

## Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By 1961 U.S.F.S.

Where filed or recorded \_\_\_\_\_

Monument 6" Concrete w/ Brass Cap  
(Original, concrete post, iron rod, etc.)

## Evidence of Subsequent Corner Restoration Found

Year of search 1981 By R. OlsonMonument in place and good condition

## Bearing Trees, Reference Objects

Species oak Cedar CedarDiameter 16" 12" 12"Bearing N76W S62E N57WDistance 9.9' 36.7' 43.0'

## Bearing Trees, Reference Objects

all BT's good4/28/81  
Ronald Olson



Index No. L-13  
(Alphabetical - Numerical)

Book 1 Pg 54

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)


RS-7150-4 (Rev. 6/13/67)  
 GPO 802-127

T. 60 R. 27 4th Mer. N.F. Chippewa County Itasca State MN.  
114 Corner common to sections 15 and 16

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
<b>Bearing Trees</b>	<b>Original Bearing Trees Found</b>
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
<b>Subsequent Corner Restoration</b>	<b>Evidence of Subsequent Corner Restoration Found</b>
Year surveyed _____ By _____	Year of search <u>1984</u> By <u>USFS G. Kosenko</u>
Where filed or recorded _____	<u>Established:</u> <u>B. Husk</u>
Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<u>Metal Post South 3.0' w/54.2 G. Robertson</u>
	<u>W. Pine 15.8" N72°E 24.00'</u>
<b>Bearing Trees, Reference Objects</b>	<b>Bearing Trees, Reference Objects</b>
Species _____	<u>ORIG. Cedar 17.5" N65°W 9.34'</u>
Diameter _____	<u>176' Cedar Metal Post</u>
Bearing _____	<u>15.8" 13.5" N57°W North</u>
Distance _____	<u>36.35 42.31 5.3'</u>

760N R27W L-13



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_

Object \_\_\_\_\_

Record distance \_\_\_\_\_

Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records of \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

5. Signature \_\_\_\_\_



Index No. L-17  
(Alphabetical - Numbered)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)29-7100-4 (Rev. 6/12/67)  
CPO 000-127T. 60N R. 27W 4 Mer. N.F. Chippewa County Itasca State Mn  
Y4 Corner common to sections 14 and 15

## EXISTING SURVEYS

## Original Government Survey

Year surveyed 1875  
Original monument 4 in X 5 in. Tamarack Post  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species Tamarack Tamarack  
Diameter 6 in 8 in  
Bearing S.50°W N.66°E  
Distance 13.86' 16.50'

## Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Wrought, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

## Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter corner lost  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

## Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_



Sketch

O Corner     F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
Object \_\_\_\_\_  
Record distance \_\_\_\_\_  
Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Corridor corner restoration certificate prepared:    Yes \_\_\_\_\_ No \_\_\_\_\_  
Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_  
Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

At time of search: \_\_\_\_\_  
1. Did you have the record description?  
Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
Pacing, chaining, photos, maps,  
etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Index No. N-13  
(Alphabetical - Subsequent)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7180-4 (Rev. 6/15/67)  
 GPO 688-127

T. 60 N R. 27 W Mer. N.F. Chippewa County Itasca State Mn  
 Section 4 Corner common to sections 15 16 21 and 22

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
 Original monument W. Birch post  
(wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	W. Birch	W. Birch	W. Birch	Fir
Diameter	12"	10"	10"	6"
Bearing	N65°W	S31°E	N27°E	S47°W
Distance	16.50'	5.28'	49.50'	19.80'

Subsequent Corner Restoration

Year surveyed Circa 1960-1970 By County  
 Where filed or recorded \_\_\_\_\_  
 Monument Found a 1" iron pipe which fits the  
remains of 3 stumps for bearing distance, +  
species. Replaced iron with county monument  
from which:

Bearing Trees, Reference Objects

Species	Basswood	Cedar	Spruce	Cedar
Diameter	10"	8"	5"	13"
Bearing	N48°W	S10°W	N61°E	S14°E
Distance	25.79'	17.41'	12.52'	42.97'

Original Evidence Found

Year of search 1934 By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found


Species			
Diameter			
Bearing	N61°W		
Distance	11.22'		

Evidence of Subsequent Corner Restoration Found

Year of search 1982 By K. Whitehorn  
 Found 2" I.P. w/3" Alum. Cap up 2.1 ft  
stump:  
16/15 All BT's Marked with Red  
21/22 Enamel, USES Tag 54-3 and  
60 d. spikes in base of BT's

Bearing Trees, Reference Objects

Species	Maple	Cedar	Spruce	Cedar
Diameter	10.5"	10.0"	8.5"	13.8"
Bearing	N42°W	S17°W	N67.5°E	S05°E
Distance	26.22'	17.72'	12.48'	43.31'



Sketch

O Corner    ▨ F.S. Land

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

- At time of search:
1. Did you have the record description?  
 Yes \_\_\_\_\_ No \_\_\_\_\_
  2. How was search area located?  
 Pacing, chaining, photos, maps, etc. \_\_\_\_\_
  3. How many hours spent in search \_\_\_\_\_
  4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document: F.S. \_\_\_\_\_  
 Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. N-13  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)


RS-5680-11 (5/12/81)

T. 60 N R. 27 W Mer. N.F. Chippewa County Itasca State Minnesota  
Section 15 Corner common to sections 15 16 21 and 22

## EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
Species <u>Field Check</u> <sup>Bearing Trees</sup> Diameter _____ Bearing _____ Distance _____	Original Bearing Trees Found Species <u>W. Spruce</u> <u>Cedar</u> <u>Cedar</u> Diameter <u>5"</u> <u>9"</u> <u>9"</u> Bearing <u>N.E.</u> <u>S</u> <u>S.E.</u> Distance <u>10'</u> <u>12'</u> <u>35'</u>
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	Year of search _____ By _____ _____ _____ _____ _____
Bearing Trees, Reference Objects	
Species _____ Diameter _____ Bearing _____ Distance _____	_____ _____ _____ _____

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner    ▨ F.S. Land

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

A county brass cap on brushed out line east of State camp ground on Long Lake on Highway No. 6 and West of Power Line that runs North & South on East side of Highway #6

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No X

2. How was search area located?

Pacing, chaining, photos, maps, etc. Photos, Pacing

3. Man hours spent in search 2

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No X

5. Signature Charles Schultz

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. N-15  
(Alphabetical - Subsequent)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7100-4 (Rev. 6/13/67)  
GPO 500-127

T. 60N R. 27W 4 Mer. N.F. Chippewa County Itasca State Ma  
1/4 Corner common to sections 15 and 22

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Elm Post 4 in x 5 in  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Spruce W. Birch  
Diameter 10" 12"  
Bearing S 10° E N 64° W  
Distance 6.60' 26.40'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Dia. \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search 1982 By K. Whitehorn + G. Kasanko  
Monument found none

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter no evidence  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
Object \_\_\_\_\_  
Record distance \_\_\_\_\_  
Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
etc. \_\_\_\_\_  
\_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might

recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Certified corner restoration \_\_\_\_\_ par. \_\_\_\_\_ Yes \_\_\_\_\_ No \_\_\_\_\_  
Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_  
Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. N-17  
(Alphabetical - Subsequent)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7160-6 (Rev. 6/15/67)  
 GPO 508-127

T. 60N R. 27W 4 Mer. N.F. Chippewa County Itasca State Mn  
 Section 14 Corner common to sections 14 15 22 and 23

EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1875

Original monument W. Birch Post  
(Wood post, stone, pile of stones, pipe, etc.)

**Bearing Trees**

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>14"</u>	<u>S 67° E</u>	<u>8.58'</u>
<u>Maple</u>	<u>10 in</u>	<u>N 56° E</u>	<u>29.70'</u>
<u>Maple</u>	<u>14"</u>	<u>S 59° W</u>	<u>26.12'</u>
<u>Basswood</u>	<u>6"</u>	<u>N 56° W</u>	<u>39.98'</u>

**Original Evidence Found**

Year of search 1982 By K. Whitehorn & E. Terriault

Monument found none

**Original Bearing Trees Found**

Species \_\_\_\_\_

Diameter no evidence

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Where filed or recorded \_\_\_\_\_

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Bearing Trees, Reference Objects**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_


**Bearing Trees, Reference Objects**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_



Sketch

Corner  F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
Object \_\_\_\_\_  
Record distance \_\_\_\_\_  
Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Certification or restoration certificate prepared: \_\_\_\_\_  
Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County \_\_\_\_\_  
Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

- At time of search:
1. Did you have the record description?  
Yes \_\_\_\_\_ No \_\_\_\_\_
  2. How was search area located?  
Pacing, chaining, photos, maps, etc. \_\_\_\_\_
  3. Man hours spent in search \_\_\_\_\_
  4. Do you think additional search might recover evidence? \_\_\_\_\_
  5. Signature \_\_\_\_\_

Index No. P-13  
(Alphabetical - Numerical)Book 1  
Page 10LAND CORNER RECORD  
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)  
GPO 802-127T. 60N R. 27W 4<sup>th</sup> Mer. N.F. Chippewa County Itasca State Minnesota  
1/4 Corner common to sections 21 22 and \_\_\_\_\_

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed \_\_\_\_\_

By \_\_\_\_\_

Where filed or recorded \_\_\_\_\_

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species Cedar Cedar

Diameter \_\_\_\_\_

Bearing S86W S24EDistance 2.0 1.1

## Original Evidence Found

Year of search \_\_\_\_\_

By \_\_\_\_\_

Monument found \_\_\_\_\_

## Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_


## Evidence of Subsequent Corner Restoration Found

Year of search 1979By Itasca Countyfound Iron in place

## Bearing Trees, Reference Objects

Species CedarDiameter 9.1 10"Bearing S86W S24EDistance 218' 14.7'

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner    ▨ F.S. Land

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

*N-1*  
*C-1*  
*1/12/11*  
*12*

*ST-1*

*Arnold*  
*6/16/11*

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. P-21  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)  
GPO 502-127

T. 60 N R. 27 W 4 Mer. N.F. nippewa County Tasca State Minnesota  
Quarter Corner common to sections 23 and 24

EXISTING SURVEYS

**Original Government Survey**

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

---

**Bearing Trees**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

---

**Original Bearing Trees Found**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Where filed or recorded \_\_\_\_\_

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

See: T60N R27W BK1 pg 26

**Bearing Trees, Reference Objects**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_


**Bearing Trees, Reference Objects**

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



Sketch

Corner  F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search 1/2

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No

5. Signature Alvin P. Kovach

Perpetuation Record

Monument and accessories established. Include brief description of area. 1-4-83

<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>	<u>12" pipe</u>
<u>14" stub</u>	<u>9.5" r</u>	<u>10.5" r</u>	<u>sp</u>
<u>N86°E</u>	<u>S13°</u>	<u>N47°E</u>	<u>1.1" N</u>
<u>7.30"</u>	<u>3.5"</u>	<u>2.15"</u>	<u>1.33"</u>



Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records of \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed of \_\_\_\_\_

Index No. P-21  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/64)

X

T. 60N R. 27W 44 Mer. N.F. Skippawa County Itasca State Minnesota  
Corner common to sections 23, 24 and

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875 GLO  
Original monument Cedar post  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees  
Species Field Creek  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1943 By Itasca County  
Where filed or recorded Itasca County  
Monument Iron Pipe  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Cedar Cedar  
Diameter 14' 12'  
Bearing N76°E N54°W  
Distance 7.3' 8.0'

Original Evidence Found


Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ◻ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections 23 24  
 Object 12" Sawed cedar 14" Sawed cedar  
 Record distance \_\_\_\_\_  
 Measured distance 13 1/2 11 1/2

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Itasca County Survey to establish lots on  
~~Section 12~~ 12

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No X

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. chaining, photo

3. Man hours spent in search 2

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No X

5. Signature J.P. Coyle

Perpetuation Record

Monument and accessories established. Include brief description of area.

Capped Iron Pipe by Itasca County  
Squared cedar stake  
Metal tag by Forest Service

**CERTIFICATE FILED**

Certified corner restoration certificate prepared: by Keith White  
 Yes \_\_\_\_\_ No \_\_\_\_\_  
 Filed in county records at Itasca Date 4/27/83 County Document No. 357066  
 Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. R-13  
(Alphabetical - Numbered)

BOOK # 1  
PAGE # 8

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RD-5680-11 (5/12/61)

T. 60N R. 27W  
Section

4th P. Mer. N.F. Chippewa County Itasca  
Corner common to sections 27, 28, 29

State Minnesota  
and 22

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_  
Diameter Needs Field Check - get  
Bearing County Water Erit-  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Itasca County  
Where filed or recorded Itasca County  
Monument Iron post  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species unknown unknown unknown unknown  
Diameter 4 2 4 4  
Bearing 4 4 4 4  
Distance 4 4 4 4

Original Evidence Found


Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections	21	22	27	28
Object	Bearing tree	B.T.	B.T.	B.T.
Record distance				
Measured distance	not known	not known	not known	not known

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source, of testimony if any. A well cut  
Random line by Itasca County  
runs from the East and ends 1.24  
chains north of corner

well cut lines by Itasca County run  
north, south and west from this corner

Perpetuation Record

Monument and accessories established. include brief description of area.  
Capped Iron pipe by Itasca County  
Metal tag by Itasca County  
Metal tag by Forest Service

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Filled in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_  
 Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No X

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Chaining, photo

Itasca County Random  
line

3. Man hours spent in search 2

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No X

5. Signature J.P. Coye

Index No. R-13Bear. Page 8LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)

GPO 602-127

T. 60N R. 27W 4<sup>th</sup> Mer. N.F. Chippewa County Itasca State Minnesota  
Sec Corner common to sections 21, 22, 27 and 28

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

## Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Itasca CountyWhere filed or recorded Itasca Co. HouseMonument Iron pipe w/ brass cap  
(Original, concrete post, iron rod, etc.)

## Evidence of Subsequent Corner Restoration Found


Year of search 1979 By R. Olesenfound Iron in pipe

## Bearing Trees, Reference Objects

Species Aspen Birch Balsam BalsamDiameter 8" 5" 5" 6"Bearing N75E S64E S46W N20WDistance 3.45' 15.05' 10.47' 11.6'

## Bearing Trees, Reference Objects

Species Aspen Birch stump Balsam BalsamDiameter 8" 5" 5" 9" 9"Bearing N75E S59E S56W N14WDistance 3.45' 15.05' 10.47' 11.6'



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area.

*To perpetuate this cor. I*

*cut New BT*

*Birch  
5"*

*575 E  
26.85'*

*set 8" Steel  
signpost  
North*

*214'*

*w/signs  
54-2 4-9*

*Ronald D. [unclear]  
6/14/79*

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records of \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. R-15  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/15/67)

GPO 502-127

T. 60N R. 27W  
1/4Mer. N.F. 4th Chippewa County Itasca State Minnesota  
22 & 27 Corner common to sections \_\_\_\_\_ and \_\_\_\_\_

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Itasca County.  
Where filed or recorded Cape Iron Pipe  
Monument \_\_\_\_\_  
(Brigpost, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species Cedar Cedar  
Diameter 3" 4"  
Bearing N51E S66E  
Distance 11.61' 14.25'

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

## Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Evidence of Subsequent Corner Restoration Found

Year of search 1981 By R. Olesen  
Monument in place and good  
condition.

## Bearing Trees, Reference Objects

Species Cedar Cedar Stump  
Diameter 4"  
Bearing N57E S60E  
Distance 11.61' 14.25'



Sketch

Corner  F.S. Land

Relation of Evidence to Record Features Along Section Lines

R-

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

*BT by some one else*

*Balson 7" N 72W 10.75'*

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area.

*To bring this corner to Standard F Cut New BT*

<i>Cedar</i>	<i>Cedar</i>	<i>Steel post</i>
<i>6"</i>	<i>7"</i>	<i>8"</i>

<i>N28W</i>	<i>N10E</i>	<i>West</i>
<i>38.07</i>	<i>28.3'</i>	<i>2.5'</i>

*4/81  
Ronald Olson*

<i>1/4 522</i>	<i>1/4 522</i>	<i>w/ signs</i>
<i>BT</i>	<i>BT</i>	<i>54-2154-9</i>

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

5. Signature \_\_\_\_\_ Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. R-21  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RR-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 60N R. 27W <sup>4<sup>th</sup></sup> Mer. N.F. Chippewa County Itasca State Minnesota  
section Corner common to sections 23, 24, 25 and 26

EXISTING SURVEYS

**Original Government Survey**

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

**Bearing Trees**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Where filed or recorded \_\_\_\_\_

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

**Bearing Trees, Reference Objects**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

See: T60N R26W BK1 pg 16


**Bearing Trees, Reference Objects**

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



Sketch

Corner  F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

At time of search:

1. Did you have the record description?  
 Yes  No \_\_\_\_\_

2. How was search area located?  
 Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search 1 1/2

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No

5. Signature Allen P. Krause

Perpetuation Record

Monument and accessories established. Include brief description of area. 10' x 10'  
2 in. outside diameter iron pipe w/ 3" diam. brass cap stamp:

Aspen 12' x 12' 1 1/2" 1 1/2"  
1/8 in 1 1/2" 1 1/2"  
1 1/4" 1 1/4" 1 1/4" 3" E  
1 1/2" 1 1/2" 1 1/2"  
metal sign post N 20° W w/ 5/8"  
metal sign post 2 1/2" 3 1/2" 1 1/2" 1 1/2"



Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. S-21  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
 GPO 802-127


T. 60 N R. 27 W 4<sup>th</sup> Mer. N.F. Chippewa County Itasca State Mn.  
N 16 Corner common to sections 26, 25 and \_\_\_\_\_

EXISTING SURVEYS


Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
<b>Bearing Trees</b>	<b>Original Bearing Trees Found</b>
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____

Corner Established Subsequent Corner Restoration Evidence of Subsequent Corner Restoration Found

Year surveyed <u>1983</u> By <u>G. Kase, B. Ausk, G. Kauter</u>	Year of search _____ By _____
Where filed or recorded <u>Itasca Co. Court House</u>	
Monument <u>3' con x 2 1/2' galv. iron pipe, concrete</u> <small>(Original, concrete post, iron rod, etc.)</small> <u>with 3' brass cap</u>	
<u>RLS # 14677</u>	



Bearing Trees, Reference Objects				Bearing Trees, Reference Objects			
Species	<u>S. Maple</u>	<u>S. Maple</u>	<u>S. Maple</u>	<u>2 metal sign</u>			
Diameter	<u>6.9"</u>	<u>10.4"</u>	<u>11.4"</u>	<u>posts-one N.</u>			
Bearing	<u>N 80° E</u>	<u>S 08° W</u>	<u>11.4</u>	<u>3.0' from E.</u>			
Distance	<u>2.78'</u>	<u>44.24'</u>	<u>2.12'</u>				



Sketch

○ Corner    ▣ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located? --

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

5. Signature *Gregory Robert Town*

Index No. 73 T-13  
(Alphabetical - Numerical)

BOOK # 1  
PAGE # 7  
4<sup>th</sup>

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

FD-5000-11 (10/12/61)

X

T. 60 R. 27 Mer. N.F. Chip County Itasca State Minn.  
Quarter Corner common to sections 27, 28 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Cedar Cedar  
Diameter 8" 14"  
Bearing N45E N83W  
Distance 60 LKS 70 LKS

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Relation of Evidence to Record Features Along Section Lines

Section line to sections 27-28  
 Object Hwy #6  
 Record distance 11.20 ch  
 Measured distance \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Note Sec 28 is only 11.20 chains wide & Hwy #6 at this point is the west bdy. of townships

At time of search:

1. Did you have the record description?

Yes X No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. Chaining - photo

3. Man hours spent in search 2

4. Do you think additional search might recover evidence? Yes X No \_\_\_\_\_

\_\_\_\_\_

5. Signature R. W. McDonald

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified o aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

T. 60N R. 27W 4<sup>th</sup> Mer. N.F. Chippewa County Itasca State Minnesota  
79 Corner common to sections 27 28 and \_\_\_\_\_

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Itasca County  
Where filed or recorded Itasca Co. Courthouse  
Monument Iron pipe w/ Alum. Cap.  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species Spruce Birch  
Diameter 10" 6"  
Bearing N10°W N68E  
Distance 9.29' 19.4'

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

## Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Evidence of Subsequent Corner Restoration Found

Year of search 1979 By R. Oleson  
Iron in place

## Bearing Trees, Reference Objects

Species Spruce Birch  
Diameter 12"  
Bearing N4W 90m  
Distance 9.29'



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections	_____	_____	_____
Object	_____	_____	_____
Record distance	_____	_____	_____
Measured distance	_____	_____	_____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc.

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area.

*To perpetuate this corner I cut New Pins*

*cedar Ced sets 1-*

*10' N. W 57SW*

*N r's*

*57.12 65.42*

*1.2' 1/2" 54 4*

*Ronald D. [Signature]*  
*6/14/79*

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_  
 Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. TU-21  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 602-127

T. 60 N R. 27 W 4<sup>th</sup> Mer. N.F. Chippewa County Itasca State Minnesota  
MC + WCMC Corner common to sections 25, 26, and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument 4" x 4" Cedar post  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species B. of Gilard Cedar  
Diameter 10" 8"  
Bearing N17°W N18°E  
Distance 53.00 ft 59.60 ft

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

See Pg. 51 BK # 1

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

TU-21 T60N R27W



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines


Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any.

1983  
 Reset the Itasca County monument 4 inches below water surface from which:

Ash	Ash	Ash
8.6 in	8.7 in	4.1 in
N175°W	N22°W	N68°E
19.12 ft	22.10 ft	16.00 ft



At time of search:

1. Did you have the record description?  
 Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_


4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. 1983

Set a 3/4 in. diameter rod monument (aluminum) with an aluminum cap, 3/4 in diam stamped:

Ash	Ash	Ash	WCMC
4.1"	8.7"	8.6"	
N127°E	N11°W	N37°W	North
31.10 ft	43.10 ft	33.50 ft	21.68 ft



References Pulled to the actual MC

Certified corner restoration certificate prepared: Yes  No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. 357247

5. Signature Phyllis P. Koontz

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. U-18,19  
(Alphabetical - Numerical)


*Block # 23*  
**LAND CORNER RECORD**  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
 GPO 502-127

T. 60 N R. 27 Mer. N.F. Chippewa County Itasca State Minnesota  
*4th*  
S 1/16 M.C. E. Shore Turtle Lake Corner common to sections \_\_\_\_\_ and \_\_\_\_\_  
26

**EXISTING SURVEYS**

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed <u>1942</u> By <u>Mr. Warner Co. Surveyor</u>	Year of search <u>1980</u> By <u>R. Olesen</u>
Where filed or recorded <u>Itasca Co. Court House</u>	found <u>1" x 16" Iron in place</u>
Monument <u>Iron</u> <small>(Original, concrete post, iron rod, etc.)</small>	<u>with cast, CT</u>
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species <u>Cedar</u> <u>Birch</u>	<u>Cedar</u> <u>Birch</u>
Diameter <u>10"</u> <u>4"</u>	<u>13"</u> <u>7"</u>
Bearing <u>S 50W</u> <u>N 14 E</u>	<u>S 56W</u> <u>N 20 E</u>
Distance <u>9.6'</u> <u>18.2'</u>	<u>9.6'</u> <u>38.44'</u>



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

U-319

Section line to sections \_\_\_\_\_

Object \_\_\_\_\_

Record distance \_\_\_\_\_

Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?  
Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
Pacing, chaining, photos, maps,  
etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_


5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area *To perpetuate*  
*This corner I set a 2" x 5' Gal Iron pipe with brass cap*  
*From which bears:*

<i>Birch</i>	<i>Spruce</i>
<i>5"</i>	<i>9"</i>
<i>N48E</i>	<i>S68E</i>
<i>35.44</i>	<i>38.44</i>

*Marked*



*7/21/80*  
*Perpetuated*

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. U-18,14  
(Alphabetical - Non/rect)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. T 60 N R. 27 W 4th Mer. N.F. Chippewa County Itasca State Minnesota  
SA Meander South 1/2 Corner common to sections 26 and \_\_\_\_\_  
Line East shore Turtle Lake

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed 1942 By P.O. Warner Itasca Co.  
 Where filed or recorded Itasca Co. Court house  
 Monument Iron pipe  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species Cedar Birch  
 Diameter 10" 4"  
 Bearing S50°W N14°E  
 Distance 9.6' 18.2'

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

## Original Bearing Trees Found


Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

## Evidence of Subsequent Corner Restoration Found

Year of search 1977 By R. Olesen  
found Iron pipe in place

## Bearing Trees, Reference Objects

Cedar Birch  
12" 6"  
S50°W N14°E  
9.6' 18.2'



Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_

Object \_\_\_\_\_

Record distance \_\_\_\_\_

Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes  No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. Chain + map.

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature Ronald Olson

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

I found the County pipe & bearing trees and put up B.T. tags on existing bearing trees painted blue line East from cur

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. U-20  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)  
GPO 802-127T. 60N R. 27W 4<sup>th</sup> Mer. N.F. Chippewa County Itasca State Minnesota  
S.E. 1/16 Corner common to sections 26 and \_\_\_\_\_

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed 1942 By P.C. Warner Co. SurveyorWhere filed or recorded Itasca Co. Court houseMonument Iron  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species Poplar Poplar [REDACTED]  
Diameter 12" 10" \_\_\_\_\_  
Bearing S53W N84E \_\_\_\_\_  
Distance 5.4' 21.6' \_\_\_\_\_

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

## Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Evidence of Subsequent Corner Restoration Found

Year of search 1980 By B. J. ESEN  
Found 2" x 3" IRON IN PLACE with  
Country 1/2"

## Bearing Trees, Reference Objects

Species Rotten Aspen Poplar \_\_\_\_\_  
Diameter 5.59 W 14 \_\_\_\_\_  
Bearing S54 W N EAST \_\_\_\_\_  
Distance 5.4' 21.6' \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

U-20

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?  
 Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
 Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_


3. Mon hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. *To perpetuate*  
*THIS CORNER I SET A 2" x 5" GAL IRON P. W/ BRASS CAP*  
*FROM WITHIN 4 FEARS*  
 CEDAR                      CEDAR  
 7"                              7"  
 N80W                      N36W  
 31.16                      41.68



7/31/89

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. U-20  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)  
GPO 802-127T. T60N R. 27W 4th Mer. N.F. Chippawa County Itasca State Minnesota  
South East 1/16 Corner common to sections 26 and \_\_\_\_\_

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed 1942 By PC. Warner Itasca Co.  
Where filed or recorded Itasca Co. Court house  
Monument Iron pipe  
(Original, concrete post, etc.)

## Bearing Trees, Reference Objects

Species Poplar Poplar  
Diameter 12" 30"  
Bearing S53°W N84°E  
Distance 5.4' 21.6'

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

## Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Evidence of Subsequent Corner Restoration Found

Year of search 1977 By R. Olsen  
found Iron pipe in place

## Bearing Trees, Reference Objects

Species Aspen Aspen  
5 1/2" dia. 1 1/2" dia.  
Diameter 14"  
Bearing S53°W N84°E  
Distance 5.4' 21.6'



Sketch  
 ○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes  No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Chaining maps

3. Man hours spent in search 1

4. Do you think additional search might

recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature Ronald Olson

Perpetuation Record

Monument and accessories established. Include brief description of area.

I found the County pipe + bearing trees and put up a B.T. tag on a bearing tree which is a 14" Aspen N84°E Mag bearing 21.6° painted blue line East + West of cor.

2/27 Ronald Olson

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records of \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_


Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



T. 60N R. 27W 4<sup>th</sup> Mer. N.F. Chippewa County Itasca State Minnesota  
S 1/16 M.C. W. Shore Corner common to sections 26 and Maple Lake

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed. <u>1942</u> By <u>Ph. Warner Co. Surveyor</u>	Year of search <u>1980</u> By <u>R. O. Lee</u>
Where filed or recorded <u>Itasca Co. Court house.</u>	<u>gone</u>
Monument <u>Iron</u> <small>(Original, concrete post, iron rod, etc.)</small>	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species <u>Birch</u> <u>Birch</u>	<u>remains of Birch stump</u> <u>Birch</u>
Diameter <u>2"</u> <u>8"</u>	<u>11"</u>
Bearing <u>N 14 W</u> <u>S 75 W</u>	<u>N 8 W</u> <u>S 80 W</u>
Distance <u>56.0</u> <u>47.7'</u>	<u>56.0'</u> <u>47.7'</u>



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

4 20, 21

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?  
 Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?  
 Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_


5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area *To perpetuate*  
*This corner E set 42" x 5' Gal Iron pipe with brass caps*  
*from which bears marked*

ASH	ASH
8"	5"
S70 W	N55 W
33.58	24.57

7/31/80  
*Ronald [signature]*



Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_  
 Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. U-20721,22  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)  
GPO 802-127T. 60 R. 27 4<sup>th</sup> Mer. N.F. Chippewa County Itasca. State Minnesota  
Sp. Meander South 1/4 Corner common to sections 26 and \_\_\_\_\_  
line West Shore Maple Lake

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Subsequent Corner Restoration

Year surveyed. 1942 By R. Warner Itasca Co.  
Where filed or recorded Itasca Co. Court house  
Monument Iron pipe  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

Species Birch Birch \_\_\_\_\_  
Diameter 2" 8" \_\_\_\_\_  
Bearing N14W S75°W \_\_\_\_\_  
Distance 56.0' 47.7' \_\_\_\_\_

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

## Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

## Evidence of Subsequent Corner Restoration Found

Year of search 1977 By R. Olsen  
found Iron pipe laying down  
on shore of Maple Lake

## Decayed Bearing Trees, Reference Objects

Species Decayed Birch stump Birch \_\_\_\_\_  
Diameter \_\_\_\_\_ 12" \_\_\_\_\_  
Bearing N14W S75°W \_\_\_\_\_  
Distance 56.0' 47.7' \_\_\_\_\_



Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes  No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. Blam Maps

3. Man hours spent in search 3

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature Ronald Blam

Perpetuation Record

Monument and accessories established. Include brief description of area.

I put up a B.T. Tug on a 12" Birch S 75° W  
 Mag. Bearing 47.7° from cor. and painted  
 blue line west from cor.

2/77 Ronald Blam

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. V-12,13  
(Alphabetical - Hieratical)

BOOK # 1  
PAGE # 6  
4TH


LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 802-127

T. 60N R. 27W Mer. N.F. \_\_\_\_\_ County \_\_\_\_\_ State 28 and 33  
MEANDER Corner common to sections \_\_\_\_\_, \_\_\_\_\_, \_\_\_\_\_, \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
<b>Bearing Trees</b>	<b>Original Bearing Trees Found</b>
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
<b>Subsequent Corner Restoration</b>	<b>Evidence of Subsequent Corner Restoration Found</b>
Year surveyed _____ By _____	Year of search _____ By _____
Where filed or recorded _____	_____
Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	_____
_____	_____
_____	_____
<b>Bearing Trees, Reference Objects</b>	<b>Bearing Trees, Reference Objects</b>
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might

recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

T. 60 R. 27 Mer. N.F. Chippewa County Itasca State MINN  
Section Corner common to sections 27, 28, 33 and 34

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Tam. Post  
(wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>S40W</u>	<u>N35W</u>	<u>N60E</u>	<u>S17E</u>
Distance	<u>15 Lks</u>	<u>5 Lks</u>	<u>25 Lks</u>	<u>35 Lks</u>

Original Evidence Found

Year of search 1961 By R.H. McDonald  
Monument found None

Original Bearing Trees Found

Species None Found  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections 33-34    28-33  
 Object Boggy Lake    Boggy Lake  
 Record distance 2.30 ch    10.50 ch  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes X No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. chaining

3. Man hours spent in search 4

4. Do you think additional search might

recover evidence? Yes X No \_\_\_\_\_

5. Signature R.H. McDonald

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified a aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_



Index No. V 15  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

T. 60 N R. 27 W Mer. 4<sup>th</sup> P N.F. Chippewa County Itasca State Minn.  
44 Corner common to sections 27 and 34 X

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees  
Species Field Check  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_


Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded Itasca county  
Monument Iron post  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects  
Species W Birch W Birch  
Diameter 6" 8"  
Bearing S 71° E N 48° W  
Distance 12.476 23.981

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections    34-27    34-27  
 Object    WB    Birch  
 Record distance    \_\_\_\_\_  
 Measured distance    312    192

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No X

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4 hrs

4. Do you think additional search might

recover evidence? Yes \_\_\_\_\_ No X

5. Signature J.D. Gorman

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Capped a iron pipe by county

metal tag by I.S.

Certified corner restoration certificate prepared:    Yes \_\_\_\_\_ No \_\_\_\_\_


Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. V-17  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)  
GPO 806-924T. 60 R. 27 4th Mer. N.F. Chippewa County ITASCA State MINN  
Section Corner common to sections 26 27 34 and 35

## EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed _____	Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____	Monument found _____
Bearing Trees		Original Bearing Trees Found	
Species _____	Diameter _____	Bearing _____	Distance _____
Species _____	Diameter _____	Bearing _____	Distance _____
Subsequent Corner Restoration		Evidence of Subsequent Corner Restoration Found	
Year surveyed <u>1969</u> By <u>Itasca Co.</u>	Where filed or recorded _____	Year of search <u>1969</u> By <u>Itasca Co.</u>	Find <u>pelaginus benchmark + BT. (T.P.)</u>
Monument <u>I.P.</u> <small>(Original, concrete post, iron rod, etc.)</small>		<u>Benchmark</u> <u>BIRCH</u>	<u>572W</u> <u>8"</u>
		<u>64.86'</u> <u>N74W</u>	<u>109.64'</u>
Bearing Trees, Reference Objects		Bearing Trees, Reference Objects	
Species <u>Benchmark</u> <u>BIRCH</u> <u>3'x4' Rock</u> <u>T-Pole</u>	Diameter <u>8"</u>		
Bearing <u>S72W</u> <u>N74W</u> <u>N53E</u> <u>S28E</u>	Distance <u>64.86'</u> <u>109.64'</u> <u>34.47'</u> <u>54.95'</u>		
	<u>TAG</u>		



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps,  
 etc. \_\_\_\_\_  
 \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might  
 recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_


Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

T. GON R. 27W Mer. N.F. \_\_\_\_\_ County \_\_\_\_\_ State 33  
MEANDER Corner common to sections \_\_\_\_\_ and 34

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
<b>Bearing Trees</b>	<b>Original Bearing Trees Found</b>
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
<b>Subsequent Corner Restoration</b>	<b>Evidence of Subsequent Corner Restoration Found</b>
Year surveyed _____ By _____	Year of search _____ By _____
Where filed or recorded _____	_____
Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	_____
_____	_____
<b>Bearing Trees, Reference Objects</b>	<b>Bearing Trees, Reference Objects</b>
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____



Sketch

Corner  F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record distance \_\_\_\_\_  
 Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. \_\_\_\_\_

At time of search:

1. Did you have the record description?

Yes \_\_\_\_\_ No \_\_\_\_\_

2. How was search area located?

Pacing, chaining, photos, maps, etc. \_\_\_\_\_

3. Man hours spent in search \_\_\_\_\_

4. Do you think additional search might recover evidence? Yes \_\_\_\_\_ No \_\_\_\_\_

\_\_\_\_\_

5. Signature \_\_\_\_\_

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Certified corner restoration certificate prepared: Yes \_\_\_\_\_ No \_\_\_\_\_

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. E-15  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/64)

T. 6<sup>0</sup> R. 27 Mer. N.F. 4<sup>th</sup> CHIPPEW County HASCO State MINN.  
114 Corner common to sections 34 CT 6.0N, R 22W, and 3  
(T 59N, R 22W)

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)Species Field Check Bearing Trees

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

## Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

## Subsequent Corner Restoration


Year surveyed \_\_\_\_\_ By Hasca CountyWhere filed or recorded Hasca CountyMonument Iron pipe  
(Original, concrete post, iron rod, etc.)

## Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

## Bearing Trees, Reference Objects

Species W. Birch W. BirchDiameter 6" 6"Bearing S.W. N.E.Distance 10 Hs 12 Hs



Sketch

○ Corner    ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections 34, T260N, R22W - Sec. 3, T59N, R22W  
 Object W. Birch ----- W. Birch  
 Record distance -----  
 Measured distance 10 1/2 ----- 12 1/2

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Well out line by Itasca County.

At time of search:

1. Did you have the record description?

Yes ----- No X

2. How was search area located?

Pacing, chaining, photos, maps, etc. Compass line and chaining from sec. corner on track road

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes ----- No X

5. Signature J.P. Coyle

Perpetuation Record

Monument and accessories established. Include brief description of area.

Capped iron pipe by Itasca County.  
Metal tag by Itasca County  
Metal tag by Forest Service

Certified corner restoration certificate prepared: Yes ----- No -----

Filed in county records at ----- Date ----- County Document No. -----

Identified on aerial photo No. ----- Which is filed at -----



Index No. 3-17  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-5680-11 (5/12/61)

X

T. 160 R. 27 Mer. N.F. Chippewa County Wisconsin State Wisconsin  
Township Corner common to sections 34-35 + 600. R 22 W and  
Sec. 2 & 3, T 59 N R 22 W

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)  
Species Field Chel Bearing Trees  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_  
Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By Itasca County  
Where filed or recorded Itasca County  
Monument Iron pipe buried in  
(Original, concrete post, iron rod, etc.)  
center of Arcadia Road

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species Cedar Stump Cedar Stump  
Diameter 12" 11"  
Bearing N.W. S.W.  
Distance 1 ch 1 ch

