

31 - - - 148 - 27
1/4 Cor. to 6 - - - 147 - 27

Temp - 3" \diamond stake 2' high.

B.T. 7" Tam. South 10' - Dead.


In swamp; just off old RR grade east of R.L. Station

Lundell - 2-11-27.

now Third River Road

old R.R. grade

Round Lake R.S.



140700

Form 874-9

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Minnesota NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147-148 R. 26 5 Mer.

1/4 Corner common to Sections
6, 31, and

DESCRIPTION OF CORNER



Corner consists of a ✓

Dimension above ground ✓ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of ✓ is located ✓

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Tam. Tam.

Diameter 3" 3"

Bearing N-50-W S-10-W

Distance 20' 6 1/2'

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

Geo. Farley
Signature

9-16-24
Date

Ranger
Title

T. _____ R. _____ Mer.

8-3027

(Make sketch of topography near Corner.)

Sec.		Sec.	
Sec.		Sec.	

Metal Location Poster is on a _____
tree _____ inches diameter, on the _____
side of _____
from which this Corner bears _____
_____ chains distant.

Give any further facts which will aid in finding this
Corner again.

