


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 13, Township 137 N, Range 32 W
5TH Principal Meridian, State of Minnesota, County of CASS

At the corner location shown on the sketch:

- On 10/21/02 found a 1 1/4" IRON PIPE IN SWAMP DOWN 1'
DATE WITH TOP RUSTED OFF
- left monument as found, lowered monument, removed monument (explain)
- On 10/21/02 Placed a 1 1/2" IRON PIPE IN PLACE OF FOUND IRON PIPE,
DATE SET STEEL FENCE POST AS WITNESS



Statement of evidence for this corner location is on back of this page. JANUARY 2005
SFT00019

I certify that this document was researched and prepared by me or under my direct supervision.

SIGNATURE _____ DATE _____ License Number 16098

Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Northeast Corner Section 13, Township 137 North, Range 32 West

The Department of Natural Resources, Division of Lands and Minerals, contacted the following offices for information regarding this corner:

MN Secretary of State
MN Department of Transportation
Cass County Highway Department
Cass County Surveyor
Cass County Auditor
Cass County Recorder

1860 The US General Land Office field notes, on file in the Secretary of State's Office, show this corner to be marked with a post and the following bearing trees were marked:

Pine 12" S 80° W 178 links (117.48')
Aspen 8" N 50° W 121 links (79.86')
Aspen 5" S 80° E 53 links (34.98')
Aspen 10" N 60° E 83 links (54.78')

1916 E.B. Horst, Cass County Survey Office, in a resurvey of Ansel Township, traversed to the area where the corner should be and stepped on a stake. Horst pulled the stake out of the water and upon examination realized it was the original GLO corner. He then was able to find all the GLO bearing tree stumps. Horst set a new post and marked the following bearing trees:

Poplar 10" N 75°30' E 67.1'
Bur Oak 5" N 65° 15' W 121.4'
Red Oak 10" S 69°30' W 265'
Red Oak 10" S 80°10' E 120.6'

1917 E.B. Horst, set a 2" x 48" iron monument for the location of the corner.

2002 In October the DNR survey crew, searched for evidence of the corner and found a 1 ¼" iron pipe in swamp with top rusted off. No bearing trees were found. The survey crew pulled out the old iron pipe and replaced it with a 1 ½" iron pipe. The iron pipe was accepted as the true location of the corner and ties were taken.

Northeast Corner Section 36 bears
Northeast Corner Section 14 bears

For more information on our survey in this area, please contact MN DNR, Division of Lands and Minerals, Survey Section, 1601 Minnesota Drive, Brainerd, MN 56401