	CERTIFICATE OF LOCATION OF GOVERNMENT CORNER NORTHEAST Corner of Section 28 Township 141 Range 31 5th P.M.
	STATE OF MINNESOTA, County ofCASS
	At the corner location shown on the sketch:
	On 3/21/80 found o 2 3/4" iron pipe with marked brass cap as per
	certificate filed in 1959 by Harold Curo. Solution
	Unplaced a
	SKETCH OF REFERENCE TIES
	1 4
	24" W. Oak
	N 13 W
	Nail in 13" R. Oak
	N 64 E 21.46' Scribed
	7" W. Oak S 82 E 15.8'
	20" Elm ()
	S 38 W 55.7'
	£3;
	S 19. W 87.7'Nail in . Scribed 11" W. Oak DEADINGS ARE ADDROYIMATE
	Statement of evidence relative to this corner location is on back of page. Statement of evidence relative to this corner location is on back of page.
	261363
	I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER contained herein was prepared by me or under County of
	my direct supervision. I hereby certify that this document was filed in the Co. Recorders office at $10:\infty$ A. M. on the
	Jay H. Atendron Z-1-8Z aday of Let. A.D., 1982 SIGNATURE DATE A.D., 1982
	Registration No. 17684 County Recorder Bendah Herdenth
İ	■ Land Surveyor, □ Professional Engineer By 4 Surveyor, □ County Engineer DOCUMENT NO. 26/363
	TELEVIOLEN SULVENIA, LE CAULIN ETITIFE DE L'ESTA DE

Statement of Evidence:

- U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 8" W. Pine S 39 W 25 links, 12" W. Pine N 53 W 35 links, 14" N. Pine N 34 E 11 links, and 20" W. Pine S 62 E 28 links.
- County Surveyor's Record Book C pages 447 and 467 show survey by E.B. Horst. Found a 4" x 4" x 48" wood stake that had been set for the corner in the fall of 1920 from three GLO bearing tree stumps and one snag.
- County Surveyor's Record Book D pages 316 and 317 show-survey by John Curo. Following new ties listed: 8" W. Oak N 88-34 W 47.50', 16" W. Oak N 8 E 36.75', 7" Birch S 55-20 E 15.75', and 14" N. Pine S 46 W 46.95'. Type of monument is not stated.
- 1959 Corner certificate by Harold Curo, RLS #3417, shows 4" x 4" x 36" wood stake found at the corner. This was replaced with a 2 3/4" x 60" capped iron pipe filled with concrete with a 3" marked brass cap. Three new bearing trees were marked: 7" W. Oak S 82-32 E 15.80', 20 R. Oak N 13-32 W 36.90', and 14" Elm S 38-16 W 55.70'. Certificate was filed 3/22/60.
- Plat of survey made by U.S. Forest Service and filed as Document No. 169486 and recorded in Book of of Misc. Plats. Survey made by Peter J. Meyer, RLS #3628. Corner monument and bearing trees set and marked by Harold Curo in 1959 are shown on plat.
- USFS technician Jim Schoonover found monument and bearing trees in good condition. Two new bearing trees were marked and are shown on this certificate. A steel sign post was set 4.2' south of the corner.
- On Jan. 11, I visited the corner and found the monument as set in 1959 in good condition. Evidence of the coriginal GLO pine stumps were found to the NW and NE. A pine stump and 12" Birch were found that agreed with the 1942 ties. All three of the 1959 tie trees were found, The two newly scribed tie trees were found as per the 1980 USFS report. Accepted the monument as marking the perpetuated position of the original corner.