Index No.	D-23

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
CS $1/16$ Corner of Section $1$ , Township $141$ , Range $30$ , $5$ P.1	И.
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On 10-26-81 found a 1"x36" brass cap monument bent, remove it,	
straighten it out and put it back in place, wire to steel post  B left monument as found, D lowered monument, D removed monument (explain)	-
Onplaced a	
SKETCH OF REFERENCE TIES	
SKETCH OF REFERENCE TIES	
6" WHITE OAK	
-N-	
# ## ## ## ## ## ## ## ## ## ## ## ## #	
B" WHITE OAK O N750 W 1	
81.97	
50'± 4.4 \(\Delta\) SIGN	
1 73:	
570° W	
6"WHITE OAK	•
¥	
not to scale	
Statement of evidence relative to this corner location is on back of page.	
i hereby certify that this document and the data OFFICE OF THE REGISTER OF DEEDS	
contained herein was prepared by me or under County of	
my direct supervision.  I hereby certify that this document was filed in the Reg. of Deeds office at 11:20 A. M. on the	
Math E. Caro 12-5-81 7 day of May A.D., 198	
Registration No. 11395 Register of Deeds Bulah Henduch	بے
△ Land Surveyor, □ Professional Engineer By MS	y
☐ County Surveyor, ☐ County Engineer ☐ DOCUMENT NO. 262614	

Ĭ

~

In 1917, Earl G. Harrington, US surveyor set a 1"x36" iron pipe with brass cap for CS 1/16 from which he made the following BT's: A 6" red oak N  $24\frac{1}{2}$  E 166 LKS and a 10" red oak N  $51\frac{1}{4}$  W 153 LKS.

On October 26, 1981, Walter Curo and Paul Johnson find the brass cap monument 1' below surface of the swamp and bent, tie it out and remove it and straighten it out and put it back in and make new BT's as shown on front. We find no trace of the original BT's.