


# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

MC \_\_\_\_\_ Corner of Section 2, Township 141, Range 30, 5 P.M.  
 STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 10-19-81 found a 1"x36" iron pipe with brass cap standing in bog, <sup>DATE</sup> drive 8' fence post along side and wire monument to it  
 left monument as found,  lowered monument,  removed monument (explain)
- On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

### SKETCH OF REFERENCE TIES



not to scale

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Walter E. Cass 12-8-81  
SIGNATURE DATE

Registration No. 11395

Land Surveyor,  Professional Engineer

County Surveyor,  County Engineer

262641  
 OFFICE OF THE REGISTER OF DEEDS  
 County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 2:35 P.M. on the 7 day of May A.D., 1982

Register of Deeds Benedict Herdman  
 By M.S., Deputy

DOCUMENT NO. 262641

In 1917, Earl G. Harrington, a US surveyor set a 1"x36" iron pipe with brass cap for the MC on the south side of Jack Lake. He made the following BT's; A 8" cedar S 21 E 81 LKS and a 10" cedar S 19½ W 65 LKS.

On October 19, 1981, Walter Curo and Paul Johnson find the brass cap monument in good condition 10" below surface in the bog. We raise it to surface and drive an 8' steel fence post along side it and wire corner to it. We did not find the original BT's. We made new BT's as shown on front.