CERTIFICATE OF LOCATION OF GOVERNMENT CORNER				
CENTER NORTH SIXTEENTH Corner of Section 30 , Township 142 , Range 30 , 5th M. STATE OF MINNESOTA, County of CASS At the corner location shown on the sketch:				
			☑ On found o GLO brass cap iron monument as set in 1917.	
		•		
	ered monument, \square removed monument (explain)			
Onplaced a				
SKETCH OF REFERENCE TIES				
1				
- N -				
	Nail in			
Nail in 9" W. Oak.	Oak N 15 W 28.52'			
N 89 W 65.51' Scribed	Scribed			
63:				
ا الله الله الله الله الله الله الله ال	·			
C3. , '				
1917-BT . 10" W. Oak				
S 63 _{-W} 52.14'				
Scribed				
	BEARINGS ARE APPROXIMATE			
Statement of evidence relative to this corner location is on back of page.				
I hereby certify that this document and the data	るとうなる OFFICE OF THE COUNTY RECORDER			
contained herein was prepared by me or under	County of			
my direct supervision.	I hereby certify that this document was filed in the Co. Recorders office at 10:05 A.M. on the			
Day H. Stenguson 9-14-82 SIGNATURE DATE	29 day of Sept. A.D., 1982			
Registration No. 12684	County Recorder Leulah Herdrich			
☑ Land Surveyor, ☐ Professional Engineer	By Ms,Deputy DOCUMENT NO. 26 5 2 5 6			
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. AC 3 2 3 6			

Statement of Evidence:

- 1917 U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 10" Oak N 3½ E 46 links and 5" Oak N 63 W 79 links.
- Robert F. Schneider, RLS #5740, surveyed plat of REHM'S ESTATES filed in October, 1971. Plat borders the east line of the NEt of the NWt of Sec. 30. His notes show GLO brass cap monument found in place and used.
- 1981 U.S. Forest Service technician W.Olson found the corner monumented with a GLO brass cap monument in good condition up 0.5'. The following bearing trees were found: 10" W. Oak S 63 W 52.14' with blaze scar overgrown. Two new bearing trees were marked and are shown on this certificate.
- 1982 On Sept. 9 I visited the corner and found items as per the 1981 USFS reports. I accepted the monument as marking the same position as when set in 1917 by the GLO resurvey based on the one bearing tree found and R.F. Schneider's traverse information.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.