CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
EAST QUARTER Corner of Section 18 ,Township 141 ,Range 27 , 5thp.M. STATE OF MINNESOTA, County of CASS At the corner location shown on the sketch:			
		☑ On 10/15/80 found a GLO brass	cap monument as set in 1919.
⊠ left monument as found, □ lowered monument, □ removed monument (explain)			
Onplaced a			
SKETCH OF REFERENCE TIES			
JA JA			
-N-	Nail in 6" W. Oak		
	N 40 E 50.69' Scribed		
	···· ?		
	• • • • • • • • • • • • • • • • • • •		
Nail in 4" W. Oak			
S 77 W 13.92'			
Scribed			
£3			
	Nail in . 5" W. Oak		
£3.	S 13 W 61.38'		
W. S.	Scribed		
	BEARINGS ARE APPROXIMATE		
Statement of evidence relative to this corner location is on back of page:			
I hereby certify that this document and the data	スフタス33 OFFICE OF THE COUNTY RECORDER		
contained herein was prepared by me or under	County of Cou		
my direct supervision.	I hereby certify that this document was filed in the Co. Recorders office at 9:40 A.M. on the		
Say H. Hevenson 9-14-82 SIGNATURE DATE	<u>5</u> day of Diec. A.D., 1984		
Registration No. 12684	County Recorder Clarkie Kaylor		
☑ Land Surveyor, ☐ Professional Engineer	By MS Deputy		
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 27 2233		

Statement of Evidence:

- U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 14" W. Pine N 78 W 94 links.
- U.S. General Land Office dependent resurvey found the corner marked by an old Government wood stake. Also found the original bearing tree N 68-45 W 94 links. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 13" N. Pine S 86-30 E 158 links and 20" W. Oak N 85 W 216 links.
- U.S. Forest Service technician G. Brama found the corner monumented with a GLO brass cap monument in good condition up 6". The following bearing trees were found: Original W. Pine stump N 69 W 62.0',

 N. Pine stump N 89 E 104.3', and W. Oak stump N 85 W 142.6'. Three new bearing trees were marked and are shown on this certificate.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- Analysis of the above data indicates that the location of this Government corner has been perpetuated. I accepted the monument as marking the corner location as when set in 1919 by the GLO resurvey based on bearing tree evidence.