CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
NORTHWEST SIXTEENTH Corner of Section 7 , Township 141 , Range 28 , 5th P.M.		
STATE OF MINNESOTA, County of		
At the corner location shown on the sketch:		
☑ On 3/11/80 found o GLO brass cap monument as set in 1918.		
DATE ☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)		
□ Onplaced a		
DATE		
SKETCH OF REFERENCE TIES		
	Nail in 10" W. Oak N 11 W 82.30'	
Nail.in - 6" W. Oak N 66 W 54.23'	Scribed	
Scribed		
€3·.))	
Nail in		
	BEARINGS ARE APPROXIMATE	
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data Contained herein was prepared by me or under County of		
my direct supervision.		
Nay H. Stevens 9-15-82 SIGNATURE DATE	the Co. Recorders office at 3:35 P. M. on the 10 day of	
Registration No. 12684	County Recorder Cloudine Kaylon	
☑ Land Surveyor, □ Professional Engineer	By MS Deputy	
☐ County Surveyor. ☐ County Engineer	DOCUMENT NO. 279373	

Statement of	Evidence:
•	
1918	U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 10" J. Pine S $43\frac{1}{4}$ E 432 links and 14" R. Oak S $22\frac{1}{2}$ W 582 links.
1980	U.S. Forest Service technician W. Olson found the corner monumented with a GLO brass cap monument under ice and leaning. Monument was straightened. The following bearing trees were found: 14" J. Pine stump at correct bearing and within 2' of record distance. Three new bearing trees were marked and are shown on this certificate.
1982	County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
1982	Analysis of the above data indicates that the location of this Government corner has been perpetuated. I accepted the monument as marking the corner location as when set in 1918 by the GLO resurvey based on bearing tree evidence.