CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
MEANDER No. 26 Corner of Section 21&22, Township 143, Range 25, 5th P.M.	
STATE OF MINNESOTA, County of CASS	
At the corner location shown on the sketch:	
On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 5/23/85 placed a <u>county monument for reference to computed</u> <pre>position based on 1900 U.S. Corps of Engineers notes.</pre>	
SKETCH OF REFERENCE TIES	
4	
 -N-	
Little Vermillion Lake	
	Comp. MC #26
15.721	Position
SEC. 21	`\18*+
	SEC. 22
Spk 10 ' Ash	
17.651	July 1
Spk 5!! Birch	Spk 4 * * Tw Ash S80E 29.93 *
S10W 8.72'	3001 23.33
Bearings are approximate	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE REGISTER OF DEEDS
my direct supervision.	County of
Lengt How 6/21/95	the Reg. of Deeds office at 3:30 P. M. on the
SIGNATURE DATE	Bosistan of Board Office A.D., 19 85
Registration No. 12684 XI Land Surveyor, Professional Engineer	Register of Deeds Clandine Kaylor By
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO 2 82 880

STATEMENT OF EVIDENCE

- U.S. General Land Office survey (set wood post) for this corner and marked the following bearing trees: 14¹ Elm S78W 4 links and 6¹ Elm S65-30E 12 links.
- 1900 U.S. Corps of Engineers topographical survey notes show this corner identified from one GLO bearing tree alive and one GLO bearing tree down.
- 1981 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1981 U.S. Forest Service office in Cass Lake was contacted for information and no resurvey information was found on this corner.
- 1976- U.S. Bureau of Land Management resurvey found no evidence of this corner. Subsequent survey by them did not attempt to reestablish this corner.
- 1981- I ran a traverse around Section 21 and found no evidence of the corner or of the bearing trees.
- After BLM resurvey had established the southeast corner of Sec. 21 from the 1900 Corps survey information, I calculated this corner position based on the same 1900 survey information. This computed location fit well with the existing shoreline. No other evidence of the corner was found. Therefore, I accepted the 1900 U.S. Corps of Engineer's survey notes as the best evidence of the corner position for marking the section line. On May 23, 1985, a 2"x2" steel post with 3"x3" aluminum cap was set on the section line 15.72' south of the corner location as a reference monument.

(See Certificate of Survey for Cass County Land Department for measurements).