

**CERTIFICATE OF LOCATION OF GOVERNMENT CORNER**

For the **Southeast Corner** of Section 20, Township 143 North, Range 26 West of the 5th Principal Meridian, STATE OF MINNESOTA, County of Cass.

On April 10, 1986, to mark this corner position, we set a 2.5 inch (outside diameter) by 60 inch long galvanized iron pipe, with a polystyrene base containing an embedded magnetized pellet, and topped with a 3 inch diameter brass tablet, up 18 inches and stamped as shown in the sketch.

**SKETCH OF REFERENCE TIES**

Top of Page is NORTH

(not to scale)


decl: 5° E

N 46° E, 65.72 feet to a 16d nail in the Northwesterly face of a 10.1 inch diameter Ash, double blazed and scribed "S21" and "BT".



8 ft. long metal post with a USFS 54-9 "LAND SURVEY MONUMENT" sign attached.

3 ft.



S 68° E, 48.98 feet to a 16d nail in the northerly face of a 4.7 inch Ash, single blazed and scribed "BT".



S-15° W, 91.99 feet to a hole punched in the north end of a 15 inch corrugated metal pipe.

All bearing trees are marked with red enamel, a USFS 54-3 "BEARING TREE TAG", and a 60d spike driven vertically into the base of the baseblaze.

Statement of evidence relative to this corner position is on the back.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

*Kenneth L. Whitehorn*  
Kenneth L. Whitehorn

Date JUN. 17 1986 Registration No. 14677

289677  
OFFICE OF THE COUNTY RECORDER

County of Cass  
I hereby certify that this document was filed in the office of the County Recorder this 24 day of June, 1986, at 9:50 A.M. and assigned DOCUMENT NUMBER 289677.

*Claudine Kaylor*  
Claudine Kaylor, County Recorder

ms

**STATEMENT OF EVIDENCE:** For the Southeast Corner of Section 20, Township 143 North, Range 26 West of the 5th Principal Meridian.

This corner position was originally established on August 27, 1872, by Eli W. Griffin, Deputy Surveyor, under contract to the General Land Office, now the Bureau of Land Management (BLM). The record of this survey is on file in the Office of the Secretary of State, St. Paul, Minnesota, and indicates that Mr. Griffin set a wood post to mark this corner position. This corner position was referenced by: a 12 inch diameter Birch that bears NORTH 70 degrees WEST, a distance of 14 links (9.24 feet); a 5 inch diameter Birch that bears NORTH 7 degrees WEST, a distance of 30 links (19.80 feet); a 5 inch diameter Maple that bears NORTH 38 degrees EAST, a distance of 30 links (19.80 feet); and an 8 inch diameter Maple that bears SOUTH 72 degrees EAST, a distance of 10 links (6.60 feet).

In the Office of Walt Curo, R.L.S., Hackensack, Minnesota, we found the record of a survey by E. B. Horst dated 1916. This record, in field book number 68, page 28, indicates that Mr. Horst found both original Birch bearing trees "plainly marked" in the Southwest and Northwest quadrants from which he set a large Cedar post to mark the corner position. He then established as references: a 6 inch diameter Maple that bears NORTH 88 degrees EAST, a distance of 39.0 feet; a 7 inch diameter White Pine that bears NORTH 57 degrees WEST, a distance of 30.5 feet; a 7 inch diameter Maple that bears SOUTH 87 degrees WEST, a distance of 39.0 feet; and a 6 inch diameter Maple that bears SOUTH 26 degrees EAST, a distance of 38.5 feet.

Recorded on page 150 of the Cass County Surveyor's Record Book C in the County Recorder's Office is a survey by James H. Flynn dated August 19, 1918. This record indicates that Mr. Flynn set a new iron monument from the two recovered original bearing trees in the Southwest and Northwest Quadrants. The record further indicates that Mr. Flynn established the following as references: a 6 inch diameter Sugar Maple that bears NORTH 88 degrees 45 minutes EAST, a distance of 29 feet; and an 8 inch diameter Fir that bears NORTH 62 WEST, a distance of 30.25 feet.

Our search for physical evidence of this corner position only revealed an old Civilian Conservation Corps (CCC) notched cedar post with a very rusted and unreadable metal tag attached. I reestablished this corner position, as monumented and shown on the front of this document, using other recovered corners and the bearings and distances from Mr. Flynn's 1918 survey record. This reestablished position falls 23 feet westerly of the recovered CCC post.