CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
East Quarter Corner of Section 1 ,Township 141 N. ,Range 28 W. , 5th P.M.		
STATE OF MINNESOTA, County of <u>CASS</u>		
At the corner location shown on the sketch:		
On 7/15/87 found a concrete monument with brass tablet		
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)		
Onplaced a		
SKETCH OF REFERENCE TIES		
Not to scale		
12" Burr Oak N 41°E 47.50' (1978 BT)		
7310" Burr Oak N 59°E 43.40' (1978 BT)		
12" Maple S 45°E 35.50'		
Trees double blazed, scribed, painted red and 54-3 Bearing Tree tag attached. Measurement taken to nail in side of tree.		
Statement of evidence relative to this corner location is on back of page. 301676		
hereby certify that this document and the data ontained herein was prepared by me or under County of		
I hereby certify that this document was filed in the Co. Recorders office at 10:00 A.M. on the		
Registration No. 11395 County Recorder Clarater Kayle		
D County Surveyor By MS DOCUMENT NO. 301676		

Statement of Evidence:	East Quarter Corner Section 1, T.141 N., R.28 W., 5th P.M.
1873	US General Land Office survey set a wood post for this conner and marked the following bearing tree: 14" N.Pine 3 S 10°W 222 lks.
1915	County Survey Record Book "B",page 572,shows a survey by N.D.Gorman. He found the old Gov't BT and an iron post.
1917	County Survey Record Book "B",page 590,shows a survey by James Flynn. He found the old BT stump. Marked new BT's: N.Pine stump S 65°W 164',9"W.Oak stump N 46-20 E 200 lks.
1918	US General Land Office dependent resurvey found stump of the original BT and 2" Galv. I.P. Alongside found I.P.,set 1"x36" I.P. with marked brass cap,set 36" in ground. New BT's: 8"Poplar S 5½°E 325 lks.,8"Poplar N 22 3/4°W 282 lks.
1919	County Survey Record Book "C",page 347,shows a survey by E.B.Horst. He found the US I.M.
1978	US Forest Service personnel, Stefan, Krause & Hansey, found I.M. graded out. Surveyed corner position in from S 1/16 and N-S 1/64 Corners on East line Section 1. Set 6"x6"x24" concrete monument with brass cap. The following bearings were marked: 6"W.Oak N 48°E 47.36',6"W.Oak N 65°E 43.20', 6"W.Oak S56°E 100.01',all scribed "W4 S6 BT". 6'Steel sign post EAST 24.8'
1979	Milo Stefan,US Forest Service Surveyor,filed Gov't Resurvey plat "E-71" and shows concrete monument as set in 1978.
1987	Walt Curo,under Forest Service contract, found concrete monu- ment inplace and the 2 NE 1978 BT's. Marked a new BT SE.