

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 29, Township 134 N, Range 30 W, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:


On NOV. 24, 1987 found a 3" CAP ON 2 1/2" IRON PIPE, 0.8' ABOVE GROUND, NO MARKINGS ON CAP.

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____

NO SCALE

SKETCH OF REFERENCE TIES



NOTE: DISTANCES MEASURED TO NAIL & DISC ON SIDE OF TREE.

Statement of evidence relative to this corner location is on back of page. 302264

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Manuel S. Lindler 12/31/87
SIGNATURE DATE

Registration No. 17008

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 3:40 P.M. on the 13 day of January A.D., 19 88

County Recorder Claudine Kayle

By ms, Deputy

DOCUMENT NO. 302264

Statement of Evidence:

R-7

North Quarter Corner Section 29, Township 134 North, Range 30 West, Cass County, Minnesota.

In 1868 the original government survey was done by N. Butler. A wood post was set to mark the corner. Two bearing trees witnessing said corner was marked, noted as follows:

28" Norway Pine North 30 degrees East, 20 links

28" Norway Pine South 8 degrees West, 33 links.

Retired State of Minnesota area forester Mr. Al Stark reported location of monument from his records and use. He believed corner was monumented by CCC's in or around 1937, however location of their notes is unknown for verification.

In 1950 and again in 1963 the Cass County Highway Department found iron pipe in place 653 feet Easterly of the P.I. to Highway #34 and Highway #1.

In 1987 State of Minnesota DNR survey crews under the supervision of surveyor Bert R. Eveland, RLS #10516 found above referenced monument and made witness ties as shown on the face of this Certificate. Following 1987 while contracted with the State for land surveying, David Landecker, RLS #17008, surveyor with the firm Landecker & Associates, Inc. found monument tied out by State survey crews and verified its location and witness ties, and further accepts this monument as the perpetuation of the corner location.

Landecker File Number 87109