

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Standard

South Quarter _____ Corner of Section 31, Township 141 N, Range 29 W, 5th P.M.

STATE OF MINNESOTA, County of Cass

Latitude: 46° 58' 47.001"
 Longitude: 94° 23' 48.739"

At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 3/14/89 placed a 2" by 48" iron pipe with brass cap and
DATE
plastic base with magnet.

Magnetic Decl: 5° East
 Not to Scale

SKETCH OF REFERENCE TIES

All distances are horizontal to nail in side of tree.



7" Maple
 N 1 W 42.55'



9" Red Oak
 N 28 E 46.76'



20" Norway Pine
 N 72 E 79.65'

Monument is located on Easterly edge of small swamp.
 8' steel sign post North 4.3'
 8' steel sign post West 4.0'

Monument Stamped
 R29W
 SC
 1/4 SB1 T141N
S 6 T140N
 1989
 RLS 17008

All trees are painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page.

311846

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

David S. Landecker
 David S. Landecker
 Date 4-28-89 Registration No. 17008

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 3:50 P. M. on the 3 day of May A.D., 19 89

County Recorder Clondine Kayler

By ms, Deputy

DOCUMENT NO. 311846

Statement of Evidence:

Standard South Quarter Corner Section 31,
Township 141 North, Range 29 West, Cass County,
Minnesota

Z-3 141-29
Bk.6 Pg.22

1863 Johnson and Thornton, U.S. Deputy Surveyors, originally established this corner position while running the 10th Standard Parallel. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 9 inch Birch North 57 degrees West a distance of 25 links; and a 12 inch Aspen North 12 degrees East a distance of 18 links.

1964 U.S. Forest Service records show the following: technician Ekstrom searched for corner, but found no evidence.

1973 U.S. Forest Service location post set in approximate corner location.

1973 and 1974 Myron Landecker, Licensed Land Surveyor Number 7452, searched for, but did not find this corner.

1986 U.S. Forest Service crews set an aerial target in the vicinity of this corner for the search and establishment of the true corner position. The target having coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.

1988 on November 10 a Landecker-Stevenson & Associates crew searched for the corner. The following information was found and noted: no evidence of 1863 bearing trees, find Forest Service Location Poster for approximate corner set in 1973. Corner was determined lost.

1989 on March 14 a Landecker-Stevenson & Associates crew set a 2 inch by 48 inch iron pipe with brass cap and plastic base with magnet at the lost, single proportion position on the arc of the 10th Standard parallel, between the Southwest corner of Section 31 and the Southeast corner of Section 32. New bearing trees were marked as shown and steel sign posts were set as noted on front of this certificate.