| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER | |
|--|--|
| East Quarter Corner of Section 24 ,Township 143N , Range 26W , 5th P.M. | |
| STATE OF MINNESOTA, County of | |
| At the corner location shown on the sketch: | |
| ☑ On 10-27-1989 found a 2½" X 28" Aluminum Post with aluminum cap. | |
| | |
| ☑ left monument as found, □ lowered monument, □ removed monument (explain) | |
| □ Onplaced a | |
| | |
| Monument Marked SKETCH OF REFERENCE TIES not to scale | |
| R26W R25W | |
| - N - S24 S19 | |
| 7 | |
| 1976 | |
| 1 | į |
| 8" Cedar X N40°W 11.60 | 6" Cedar N46°E 13.97 |
| (1976) | Steel Post |
| | North 4.0 |
| SEC.24 | O SEC. 19 |
| 330.24 | |
| | 4" Cedar \$71°E 20.49 |
| | |
| | |
| | |
| | |
| All turns are provided assistant as 200 | |
| All trees are scribed, painted with a 30d bearings are true spike in side and USFS 54-3 tag. | |
| Statement of evidence relative to this corner location is on back of page. 319618 | |
| I hereby certify that this survey, plan or | OFFICE OF THE COUNTY RECORDER |
| report was prepared by me or under my | County ofCarr |
| direct supervision and that I am a duly . Registered Land Surveyor under the laws | i hereby certify that this document was filed in the Co. Recorders office at 10120 A.M. on the |
| of the State of Minnesota. | 12day of Cpil A.D. 19 90 |
| William C. Oraspa- | County Recorder Clandin Kaylu |
| | By,Deputy |
| Date 3/20/90 Registration No. 17767 | DOCUMENT NO. 3/9/6/8 |

Statement of Evidence:

P25 East quarter corner section 24

1/4 Cor. 24 and 19 (E 1/4 Cor. Sec. 24)

1872 U.S. General Land Office survey set wood post for corner and the following references were noted:

Tamarack 6" N 15 degrees 30 minutes E, 6 Links (3.96

feet)

6" N 37 degrees W, 4 Links (2.64 feet) Cedar

4-6-1966 James Ekstrom, USFS, chained to area from approximate

section corner to north, area under snow and water,

more search needed.

James Ekstrom, USFS, did additional search, found no 7-25-1966

evidence.

1976 BLM dependent resurvey, found no original evidence, at

proportionate distance they set a 2.5"x 28" aluminum post with an aluminum cap and witnessed as follows: Cedar 8" N 40 degrees W, 17.5 Links (11.55 feet) Cedar 6" N 46 degrees E, 21 Links (13.86 feet)

10-27-1989 Personnel from Kovanen & Osufsen Inc. found 1976 BLM

monument in good condition and the following

witnesses:

Cedar 8" N 40 degrees W, 11.60 feet

Cedar 6" N 46 degrees E, 13.97 feet

we add the following witness:

Cedar 4" S 71 degrees E, 20.49 feet

Steel sign post with sign attached, North, 4.0

This position is not traceable to the original GLO corner, but accepted as corner for lack of further evidence.