CERTIFICATE OF LOCATION OF GOVERNMENT CORNER East Quarter Corner of Section 2 ,Township 143N ,Range 26W , 5th P.M.	
STATE OF MINNESOTA, County of _Cass	
At the corner location shown on the sketch:	
Onfound a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 3-21-1990 placed a 2" X 48" brass capped monument	
DATE	
Monument Marked SKETCH OF REFERENCE TIES not to scale	
1/4 T143N R26W	
-N-S2 S1 1990	5" Cedar N58°E 20.31
RLS 17767	1
SEC. 2 5" Cedar S53°W 8.37	SEC. 1 Steel Post East 2.5 Steel Post South 2.8 Steel Post South 2.8 trees are scribed, painted with a 30d
bearings are true spike in side and USFS 54-3 tag.	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.	OFFICE OF THE COUNTY RECORDER County of
Date 8/22/90 Registration No. 17767	DOCUMENT NO. 323148

Statement of Evidence:

C21 East quarter corner section 2

1/4 Cor. 1 and 2 (E 1/4 Cor. Sec. 2)

U.S. General Land Office survey set wood post for 1872 corner and the following references were noted: Tamarack 8" N 60 degrees E, 4 Links (2.64 feet) Tamarack 6" S 75 degrees W, 6 Links (3.96 feet)

11-6-1989 Personnel from Kovanen & Osufsen Inc. search area, no large trees remain in this area.

3-21-1990 Personnel from Kovanen & Osufsen Inc. set a 2" x 48" brass capped monument by single proportion measurement and on line, between the Northeast corner of Section 2 and the Southeast corner of Section 2, witnesses are as follow:

> Cedar 5" N 58 degrees E, 20.31 feet Cedar 5" S 53 degrees W, 8.37 feet Cedar 6" S 72 degrees E, 6.20 feet

Set 8' long steel sign post with sign attached, East 2.5 feet

Set 8' long steel sign post with sign attached, South

.

2.8 feet

This position is not traceable to the original GLO corner, but accepted as corner for lack of further evidence.