| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER | |
|---|---|
| NORTHEAST Corner of Section 10 Township 134 N Range 30 W , 5th P.M. | |
| STATE OF MINNESOTA, County ofCASS | |
| At the corner location shown on the sketch: | |
| ⊠ On 6-28-93 found a 7/8" IRON ROD, DOWN 0.1" | |
| | |
| | · |
| On Placed a | |
| | |
| SKETCH OF REFERENCE TIES | |
| N | |
| - | |
| 12 | ON CL E-W ROAD ON CL ROAD NORTH |
| <u> </u> | 1 |
| ا ا | 1 |
| 1 | 1 |
| | |
| | |
| ave. | |
| FOUND NAIL & DISC SE SIDE 4" ASH | |
| UP 8.0' | S 40° E 84.78° |
| S 18' W | FOLIND NAIL & DISC |
| 72.04 | S 15' E NE SIDE 5" OAK 78.77' UP 6.0' |
| Kry Series | |
| FOUND NAIL & DISC | Even Vile |
| WEST SIDE 8" OAK UP 6.0' | (Constant of the constant of |
| BEARINGS OBSERVED WITH COMPASS | |
| Statement of evidence relative to this corner la | ocation is on back of page. J.B.M. Aug. 1993 |
| I hereby certify that this document and the data | OFFICE OF THE COUNTY RECORDER 35/9/3 |
| contained herein was prepared by me or under | County of CASS |
| my direct supervision. | I hereby certify that this document was filed in |
| SIGNATURE DATE | the Co. recorders office at 4:16 PM. on the |
| Registration No. 17005 | County Recorder Claudine Kaylan |
| ■ Land Surveyor, □ Professional Engineer | By,Deputy |
| ☐ County Surveyor, ☐ County Engineer | DOCUMENT NO |

Northeast Corner Section 10, Township 134 North, Range 30 West

The DNR Bureau of Engineering contacted the following offices for information regarding this corner:

MN Secretary of State Cass County Surveyor Cass County Highway Engineer

1868 The U.S. General Land Office field notes, on file in the Secretary of State's Office, show this corner to be marked with a post and marked the following bearing trees:

Pine 26" N 50° E 10 lks., Pine 25" S 12° E 28 lks.

Pine 18" S 26° W 37 lks.

- 1914 Cass County Land Corner Record Card, on file in the County Surveyor's Office, shows in County Survey Record Book B, on Pages 32 to 34, John Curo found all of the government bearing trees. Set a 2 1/2" x 48" galvanized iron pipe with cap.
- 1915 Cass County Land Corner Record Card, on file in the County Surveyor's Office, shows in County Survey Record Book B, on Pages 494 to 495, N.D. Gorman found the corner. This information is also on microfilm roll 115 Book 79 Page 129. Two reference ties are shown:

W. Pine Stump 30" S 63° E 44.78 ft., N. Pine Stump 24" N 53° E 54.88 ft.

- No The right-of-way map for County State Aid Highway 15 shows an inplace monument Date at this corner. Corner is shown at the intersection of roads east-west and north.
- 1990 Cass County Land Corner Record Card, on file in the County Surveyor's Office, shows W. Curo set a pin and temporary ties with a county highway crew.
- June 28, the DNR Bureau of Engineering conducted a search for the corner and found a 7/8" iron rod, down 0.1 feet. Iron rod is at the intersection of roads east-west and north. Searched for and found the 1990 ties which were found to agree with the iron rod. No other record ties could be found. Iron rod was found to measure:

2652.96 ft. from the north quarter corner Section 11

2650.55 ft. from the east quarter corner Section 10

2624.05 ft. from the north quarter corner Section 10

Analysis of the available information led the DNR Bureau of Engineering to conclude that the iron rod marks the location of the corner. It is unknown if the iron rod was set inplace of the 1914 monument set by John Curo, however its relative location is in agreement with local occupation.