

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter _____ Corner of Section 26, Township 141, Range 27, 5th P.M.


STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:


- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 3/4/94 placed a 2 inch by 24 inch iron pipe with brass cap
DATE over an 8 foot steel sign post, up 19 inches.

Magnetic Decl: 5° East SKETCH OF REFERENCE TIES
Not to Scale

All distances are horizontal to nail in side of tree.



Monument is located in a low area 85'± northerly of old trail through swamp. 8' steel sign post North 2.1'.



Monument Stamped:
T141N R27W
 $\frac{1}{4}$ S23
S26
1994
RLS No. 21367

All trees are scribed, painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page.

357308

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

Terry L. Freeman
Terry L. Freeman
Date 5/4/94 Registration No. 21367

OFFICE OF THE COUNTY RECORDER
County of CASS

I hereby certify that this document was filed in the Co. Recorders office at 9:40 A. M. on the 4th day of MAY A.D., 19 94

County Recorder Claudia Kaylar
By N.B. CLAUDE J. JENSEN, Deputy
DOCUMENT NO. 357308

Statement of Evidence:

North Quarter corner, Section 26, Township 141
North, Range 27 West, Cass County, Minnesota

R-19

1874 P.H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 141 North, Range 27 West. The notes indicate that he set a wood post and marked the following bearing tree: a 6 inch Cedar North 20 degrees East a distance of 40 links (26.40 feet).

1968 United States Forest Service notes for Township 141 North, Range 27 West, in Book 2, Page 40, in United States Forest Service files in Cass Lake, Minnesota, show that technicians traveled by this corner but found it quite impractical to search as all standing trees were quite small.

1993 in October, a Landecker & Associates, Inc. survey crew compass and chain into area of corner. They searched for original survey evidence and found nothing. They then traverse into area in December and found original search area to be same as computed location from traverse.

1994 on March 4, a Landecker & Associates, Inc. survey crew make a final search for original survey ties and post, finding nothing, they set a 2 inch by 24 inch iron pipe with brass cap over an 8 foot steel sign post. New bearing trees were marked and steel sign posts set as noted on front of this certificate.

This corner is set at the lost, single proportion position between the Northwest and Northeast corners of Section 26.