



8 0 0 9 9 0 1
Tx:4007001

A000561972

**OFFICE OF COUNTY RECORDER
CASS COUNTY MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON
07/20/2010 12:31:04 PM
AS DOC #: A000561972
PAGES: 2 REC FEES: 0.00
KATHRYN M. NORBY
COUNTY RECORDER**


Index No. A-23

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

 NORTH QUARTER Corner of Section 1 ,Township 140 N ,Range 31 W
 5TH Principal Meridian, State of Minnesota, County of CASS

At the corner location shown on the sketch:

- On found a
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 3/30/06 Placed a 3/4" IRON ROD WITH SURVEY CAP DOWN 0.3'
DATE 7' SOUTH OF CENTERLINE ROAD



Statement of evidence for this corner location is on back of this page.

MAY 2006
AMA00119

I certify that this document was researched and prepared by me or under my direct supervision.

SIGNATURE DATE 9/11/06 License Number 16098

Title: Land Surveyor Professional Engineer County Surveyor County Engineer

North Quarter Corner Section 1, Township 140 North, Range 31 West

The Department of Natural Resources, Division of Lands and Minerals, contacted the following offices for information regarding this corner:

MN Secretary of State
 Minnesota Department of Transportation
 Cass County Surveyor's Office
 Landecker & Associates, Inc.
 Northern Lights Surveying and Mapping
 Cass County Recorder's Office

- 1863 The US General Land Office field notes, on file in the Secretary of State's Office, show this corner to be on the 10th Standard Parallel. The Standard Parallel was surveyed for and noted the section information for the sections in Township 141 North. The west line of Section 1 was not surveyed because it is entirely in Ten Mile Lake. The north line of Section 1 Township 140 North was not surveyed and therefore nothing was set for this corner. The distance on the GLO plat listed the north line of Section 1 as 55.36 chains (3653.76')
- 1957 Harold Curo's field notes show a distance of 1099.8' to the meander corner. The north-south quarter line is shown as being parallel with the east line of the section. A distance of 5090.43' was listed as the distance for the north-south quarter line.
- 1978 Plat of HILLAWAY EAST recorded and filed in the Cass County Recorder's Office, show an iron pipe established for the corner. HILLAWAY EAST is in Government Lot 3 Section 1 and no other section subdivision is shown. A distance to the meander corner is 1057.20'
- 2005 In September the DNR survey crew searched for evidence of the corner and found an iron pipe lying in the ditch in the vicinity of the corner. They found Meander Corner # 20 on the east side Ten Mile Lake, South Quarter corner Section 36, Southeast Corner Section 36. Extensive work was done to establish a section subdivision.
- 2006 In March the Northeast Corner of Section 1 was established and a lost position was computed for the corner. A bent line proportion computed on line between the Southeast Corner and the South Quarter Corner of Section 36 at a proportional distance of 40/55.36 between the Northeast Corner Section 1 and the meander corner. A 3/4" iron rod with survey cap was set at that position and ties were taken.
- Southeast Corner Section 36 bears N88°35'12"E 1984.27'
 - South Quarter Corner Section 36 bears S88°35'12"W 656.17'
 - Meander Corner bears S88°27'59"W 1013.90'
 - Northeast Corner Section 1 bears N88°34'49"E 2640.37'

For more information on our survey in this area, please contact MN DNR, Division of Lands and Minerals, Survey Section, 1601 Minnesota Drive, Brainerd, MN 56401