

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Northeast corner of Section 01, Township 143 N., Range 31 W., 5th P.M.
 State of Minnesota, County of Cass

At the corner location shown on the sketch:

On 06-21-2011 found a 3" iron pipe with a brass cap leaning, could not set upright because of roots.

left monument as found lowered monument removed monument (explain)

On 06-21-2011 placed a 1/2" diameter rebar, 4' long, with a 3.5" diameter brass cap,
 flush with the surface grade and set 1918 GLO iron alongside.

8 0 3 2 9 3 1
 TX: 4023348



SKETCH OF REFERENCE TIES (NOT TO SCALE)

**SECTION 36,
T144N, R31W**

Set New Tie:
 Set nail in southwesterly face
 of a 14" Cedar, 3" above
 ground, with a USFS tag that
 reads "J.S.D.M. 02-21-80".

**SECTION 31,
T144N, R30W**

Set New Tie:
 Set nail in northwesterly face
 of a 10" Cedar, 30" above
 ground, with a USFS tag that
 reads "J.S.D.M. 02-21-80".

1930 Tie:
 Set nail in northwesterly face
 of a 12" Cedar, 9" above
 ground, with a USFS tag that
 reads "J.S.D.M. 02-21-80".

1930 Tie:
 Found a nail in the southwesterly
 face of a 12" Cedar, 24" above
 ground, with a USFS tag that
 reads "J.S.D.M. 02-21-80".

**SECTION 1,
T143N, R31W**

**SECTION 6,
T143N, R30W**

NOTE: All bearings are true.

Statement of evidence relative to this corner location is on the back of this page.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed land Surveyor under the laws of the State of Minnesota. I further certify that this United States public land survey monument record is correct and complete to the best of my knowledge and belief.

Terry L. Freeman, Land Surveyor

Date 12/9/11 MN License No. 21367

A000578295
OFFICE OF COUNTY RECORDER
CASS COUNTY MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON
03/01/2012 2:29:31 PM
AS DOC #: A000578295
PAGES: 2 REC FEES: 0.00
KATHRYN M. NORBY
COUNTY RECORDER

Index No. A.0 - 25.0

STATEMENT ON EVIDENCE

Northeast Corner of Section 1, Township 143 North, Range 31 West of the 5th Principal Meridian.

In 1875, B.C. Baldwin, U.S. Deputy Surveyor, set a wood post in place to mark the location of this corner and established bearing trees as follows: an 8" Tamarack, S46°E 271 links; a 6" Cedar, S42°W 44 links; a 10" Cedar, N3°E 5.30 chains; and a 6" Cedar, N3°W 4.70 chains.

1900, U.S. Army Corp of Engineers map for the Leech Lake Reservoir shows corner found by surveyor Horace Dunaway. A copy of the map is on file in the Cass County Survey Department.

In 1920, Albinus N. Kimmell, U.S. Cadastral Engineer, found badly decayed wood stake, the northeast and northwest BT's, and the southeast Tamarack BT (dead). He set a 3" x 36" iron pipe with stamped brass cap and marked BT's: a 4" Cedar, S30°E 25 links; a 4" Cedar, S49°W 27 links; and a 14" Cedar, N3°W 466 links. Information on file in the Cass County Surveyors office.

In 1980, J.S. and D.M., U.S.F.S. personnel, places BT tag on the southeast and southwest 1920 BT's and set BT tags on two new bearing trees: a 14" Cedar, N32°W 19.50 feet and a 10" Cedar, N48°E 19.60 feet. Information on corner card in U.S.F.S. Cass Lake office.

On June 21, 2011, a Northern Engineering & Consulting survey crew found the 1920 GLO monument leaning, the southeast and southwest 1920 BT's, and the two 1980 BT's. The monument could not be set upright or lowered without damage. They set a 1/2" x 4" long rebar with a stamped brass cap and set 1918 GLO iron alongside. The corner position is accepted as a perpetuation of the original corner.

Minnesota State Plane (Central Zone)

Northing 1143477.044
Easting 2553489.859

County Coordinates (Cass County North)

Northing 257734.549
Easting 420540.54

