



A000608289

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

12/18/2014 10:49:13 AM

AS DOC #: A000608289

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER

BY SR Dep

Twp 142 Rge 27 Index No. D.0-06.0

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


SW Sixteenth corner of Section 5, Township 142 N., Range 27 W., 5th P.M.
State of Minnesota, County of Cass

At the corner location shown on the sketch:


On 8 July 2009 found a 1 inch outside diameter iron pipe with GLO brass cap,
up 0.5 foot.

left monument as found lowered monument removed monument (explain)

On _____ placed _____



SKETCH OF REFERENCE TIES NOT TO SCALE



NOTE:
All bearings are true

Statement of evidence relative to this corner location is on the back of this page.

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Terry L. Freeman, Cass County Surveyor
Date 12/17/14 MN License No. 21367





Index No. D.0-06.0

Statement of Evidence

South West One Sixteenth corner Section 5, Township 142 North, Range 27 West, 5th Principal Meridian.

1920 E.G. Harrington, U.S. Cadastral Engineer, assisted by D.B. Clement, U.S. Surveyor, GLO, Reestablishment of a portion of the Exteriors and Subdivisional Lines Township 142 North, Range 27 West, on file with the Minnesota Historical Society in St. Paul, Minnesota, copies are filed with the CCHD/SO, states "Set an iron post, 3 ft. long, 1 ins. diam., 26 ins. in the ground, for the S. W. 1/16 sec. cor. with brass cap". Lists the following witnesses:
10" Maple N 87 3/4° W 76 links(50.16 feet) 8" Maple N 39 1/4° E 43 links (28.38 feet)

March R. Main, technician, United States Department of Agriculture Forest Service (USFS), T 142N R 27 W Book 3, 1993 page 13, on file in the USFS Cass Lake Office, states Found GLO monument next to split rail fence post, up 6 inches, 3 feet South of fence post on east edge of field and gravel pit. Witness as follows:

4" R. Oak	N 58° E	51.68 feet	Steel Sign Post	East	5.6 feet
4" Ash	S 79° E	24.40 feet	Steel Sign Post	South	4.85 feet

July B. Hippen, technician, records of the CCHD/SO, found 1 inch outside diameter iron pipe, with GLO brass cap, 2009 up 0.5 foot at edge of old field. USFS 1993 Ash is down. New witnesses as follows:

18" Maple	S 45° E	3.93 feet	Steel Sign Post	East	6.7 feet
-----------	---------	-----------	-----------------	------	----------

The monument, recovered and established references for the position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument recovered by CCHD/SO in 2009 is the accepted location of this corner.

County Coordinates (Cass County North)

Northing 223845.61

Easting 521069.54