1 of 2 A000622981	ACCUGE 2981 OFFICE OF THE COUNTY RECORDER CASS COUNTY, MINNESOTA CERTIFIED, FILED, AND/OR RECORDED ON 7/14/2016 10:44:25 AM AS DOC #: ACCUGE ACCUGE ACCUGE ACCUGE ACCUGE ACCUGE ACCUGE ACCUGE ACCUMENT ACCURATE ACCUMENT
9	wp <u>145</u> Rge <u>31</u> Index No. <u>E.0-05.0</u>
CERTIFICATE OF LOCATION	
	wnship <u>145 N.</u> ,Range <u>31 W.</u> , <u>5th</u> P.M.
State of Minnesota, County of Cass	
At the corner location shown on the sketch On 21 April 2016 found a telspar po	
	and County Road #150.
☐ left monument as found ☐ lowered	monument 🛛 removed monument (explain)
	of new centerline County Road #75.
WO TO TO	SCALE 16d duplex nail up 2.4 feet in W. side of a Power Pole
S7 S8 2016 RLS21367	SECTION 5
is marked SECTION 6	Open
\ \ 	Centerline County Road #60
Centerline County Road #150	
SECTION 7	Section 8
//5	integral of the state of the st
	-()-
	16d duplex nail up 1.8 feet in S. side of a Power Pole
Open up 1.2 foot in S. side NOTE: All bearings are true	Wooded
Statement of evidence relative to this corner location is on the back of this page.	
I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.	
Terry L. Freeman, Cass County Surveyor Date 1/3/6 MN License No. 21367	



Page 2 of 2 A000622981

Index No. E.0-05.0

Statement of Evidence

Northeast corner of Section 7, Township 145 North, Range 31 West, 5th Principal Meridian.

June J. Usher, Deputy County. Surveyor, Road Calendar Book A, page 63 and Road Calendar Book B, page 17, on file at the Minnesota Historical Society, St. Paul, Minnesota, scanned copies are filed with the Cass County Highway Department, Surveyors Office(CCHD/SO), Indicates a position for corner in Cass Lake Road survey.

May G. Weetmen Ditch Shelf 1, Book 17, page 8, on file in the CCHD/SO, indicates corner at PI station 156+79.4. 1920

March P.J. Meyer, LS 3628, Certificate of Survey for Carlson, copy on file in the CCHD/SO, Indicates the subject corner.

Aug. W.E. Curo, LS 11395, Certificate of Location of Government Corner, on file in the Cass County Recorders
 Office as Document #325739, Set a 2 inch telspar monument with aluminum cap, flush, on centerline of County Road #75 and witnesses as follows:

7" J. Pine S 45° E 99.70 feet Power Pole N 35° E 160.66 feet Power Pole N 80° W 100.18 feet Guy Pole S 45° W 78.85 feet

March R.W. Murray, LS 15483, Certificate of Survey for Minnesota Department of Transportation(MNDOT) Indicates the subject corner.

Nov. B. Hippen, technician, records of the CCHD/SO, found an aluminum capped telspar monument, flush, 0.5 foot west of centerline of County Road #75 and 1 foot, more or less north of centerline of County Road #60, the 1990 witness Poles are good, add the following witness:

6" R. Oak S 48° E 105.52 feet

July A.D. Larson, LS 14455, Certificate of Survey for Schulman Land Division, copy on file in the CCHD/SO, Indicates 2006 2 inch square iron with broken alum. Cap, at the subject corner.

April T. Anderson, technician, records of the CCHD/SO, prior to reconstruction of County Road #75, found Telspar post cap gone, removed monument after witnessing as follows:

 Power Pole(1990)
 N 35° E
 160.66 feet
 Guy Pole(1990)
 S 45° W
 78.85 feet

 Power Pole
 S 50° E
 70.22 feet
 Elec. Meter Post
 N 40° W
 83.91 feet

July B. Hippen, technician, records of the CCHD/SO, after construction of County Road #75, set an aluminum Cass County monument, in place of the recovered telspar post, down 0.05 foot, on new centerline of County Road #75 and County Road #150, 16 feet, more or less, south of centerline County Road #60.

The monument, recovered and established references for the position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument set by CCHD/SO is the accepted location of this corner.

County Coordinates (Cass County North)

Northing 316538.79 Easting 392754.21