



**A000670644**

**OFFICE OF THE COUNTY RECORDER  
CASS COUNTY, MINNESOTA  
CERTIFIED, FILED, AND/OR  
RECORDED ON**

**3/26/2021 12:32:57 PM**

**AS DOC #: A000670644**

**PAGES: 2**

**REC FEES: 0.00**

**KATHRYN M. NORBY  
CASS COUNTY RECORDER**

**BY NG Dep TX#: 170246**

I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.

Guy T. Carlson 2/25/2021  
GUY T CARLSON DATE

LICENSE NO. 40991

- LAND SURVEYOR       PROFESSIONAL ENGINEER
- COUNTY SURVEYOR       COUNTY ENGINEER

NAD 1983 (1996 HARN) CASS COUNTY NORTH ZONE COORDINATES  
N= 330680.498 E= 450610.917 US SURVEY FT  
(COORDINATES ARE SHOWN AS INFORMATION ONLY, SUBJECT TO VERIFICATION)

## CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

INDEX NO. T-01, EAST QUARTER CORNER OF SECTION 25, TOWNSHIP 146, RANGE 30, 5TH P.M.  
STATE OF MINNESOTA, COUNTY OF CASS

AT THE CORNER LOCATION SHOWN ON THE SKETCH:

- ON 7/10/2020 FOUND A(N) STAMP BRASS CAP ATTACHED TO A 1" BY 36" IRON PIPE UP 4"
- LEFT MONUMENT AS FOUND,       LOWERED MONUMENT,       REMOVED MONUMENT (EXPLAIN)
- ON \_\_\_\_\_ DATE PLACED A(N) \_\_\_\_\_

### SKETCH OF REFERENCE TIES

DECLINATION 0°  
SKETCH NOT TO SCALE



MONUMENT MARKED:



BELTRAMI COUNTY

CASS COUNTY

A 60d spike and washer in the base of a 17½" Norway Pine. Est. 1974

A 60d spike and washer in the base of a 12½" Norway Pine. Est. 1974

A 60d spike and washer in the base of an 11" Norway Pine. Est. 1974

20.32'  
N57°W

6.28'  
S57°W

6.30'  
S32°E

T146-R30-S25

T146-R29-S30

STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON BACK OF PAGE

Page 5 of 7  
A000670644



**STATEMENT OF EVIDENCE:** East Quarter Corner of Section 25, Township 146 North, Range 30 West, of the 5th Principal Meridian.

1873; This corner was originally established by P.H. Conger, Deputy Surveyor under contract to the General Land Office (GLO), now the Bureau of Land Management (BLM). A copy of the plat of this township and hand copied field notes are available on the BLM website. These Field notes indicate a wood post was set to mark this corner position, which was witnessed by:

Norway Pine,	20", North 58° East,	42 links,	27.72 feet;
Norway Pine,	25", South 40° West,	37 links,	24.42 feet:

1933; (May) A Dependent Resurvey of a portion of T146N-R30W was performed by Cadastral Surveyor Hal D. Craig of the BLM. Mr. Craig affixed a brass cap to a 36" by 1" iron pipe from the remains of the GLO witness trees described as follows:

Burned Norway Pine stump,	24", North 58° East,	42 links,	27.72 feet;
Burned Norway Pine stump,	30", South 40° West,	37 links,	24.42 feet;

He added the following witnesses:

Red Oak,	3", South 13½° East,	74 links,	48.84 feet;
Red Oak,	3", South 41° West,	38 links,	25.08 feet:

1974; (October) C. Krause, a survey technician for the United States Forest Service (USFS) recovered the 1933 monument in good condition, 4" above the ground. Both witnesses from 1934 were recovered as well as evidence of the 1873 witnesses. He added the following witnesses:

Norway Pine,	14", North 37° West,	20.1 feet;
Norway Pine,	16", North 43° East,	32.2 feet;
Norway Pine,	8", South 53° West,	6.4 feet;
Norway Pine,	8", South 41° East,	6.4 feet;
Steel Fence post,	South,	1.2 feet:

1978; (November) Milo E, Stefan, Registered Land Surveyor #12261, while working for the USFS, drafted a Certificate of Location of Government Corner based upon the 1974 visitation. This document was recorded in Beltrami County as Document No. 257247.

2020; (July) Itasca County Department of Surveying and Mapping personnel G. Robertson and T. Lasecki recovered the 1933 monument along with three witness trees from 1974. Geodetic coordinates were established on the monument using a Fast Static observation. This information is found in the Itasca County 146-29 Field Book 2, page 28. The recovered witnesses are as shown on the face of this certificate.

***The chain of history indicates that this position is a direct perpetuation of the corner as established in 1873.***