



A000693331

**OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON**

5/2/2023 10:10:39 AM

**AS DOC #: A000693331
PAGES: 2
REC FEES: 0.00**

**KATHRYN M. NORBY
CASS COUNTY RECORDER
BY KF Dep TX#: 188768**

I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.

Guy T Carlson 4/24/2023
GUY T CARLSON DATE

LICENSE NO. 40991

- LAND SURVEYOR PROFESSIONAL ENGINEER
- COUNTY SURVEYOR COUNTY ENGINEER

NAD 1983 (1996 HARN) CASS COUNTY NORTH ZONE COORDINATES
N= 284544.572 E= 591346.292 US SURVEY FT
(COORDINATES ARE SHOWN AS INFORMATION ONLY, SUBJECT TO VERIFICATION)

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

INDEX NO. E-11, QUARTER CORNER OF SECTIONS 4 & 9, TOWNSHIP 144, RANGE 25, 5TH P.M.
STATE OF MINNESOTA, COUNTY OF CASS

AT THE CORNER LOCATION SHOWN ON THE SKETCH:

- ON 02/14/2023 FOUND A(N) bent aluminum rod with stamped cap.
- LEFT MONUMENT AS FOUND, LOWERED MONUMENT, REMOVED MONUMENT (EXPLAIN)
- ON DATE PLACED A(N)


SKETCH OF REFERENCE TIES

DECLINATION 1° EAST
SKETCH NOT TO SCALE



T144-R25-S4

MONUMENT MARKED:



Page 1 of 2
A000693331

T144-R25-S9

STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON BACK OF PAGE

STATEMENT OF EVIDENCE: Quarter Corner of Sections 4 and 9, Township 144 North, Range 25 West, of the 5th Principal Meridian.

- 1876; This corner was originally established by Benjamin Baldwin, Deputy Surveyor under contract to the General Land Office (GLO), now the Bureau of Land Management (BLM). A copy of the plat of this township and hand copied field notes are on file in the Itasca County Surveyor's Office. These Field notes indicate a wood post was set to mark this corner position, with no trees nearby suitable for witnesses.
- 1984/85; James Parker of Advance Surveying & Engineering Co. performed a Dependent Resurvey of T144N R25W for the United States Forest Service. Parker's field crew searched for but failed to find any evidence of this corner position. They set an aluminum rod with a stamped cap at a proportioned position between the southeast and southwest corners of Section 4. Mr. Parker then recorded a Certificate of Location of Government Corner as Doc. No. 281671 in the Cass County Recorder's Office. This corner position was witnessed by:

8' Steel Fence Post with Sign 54-9 WEST, 4.80 feet

- 2023; Itasca County Field Book 1, page 49. Itasca County personnel found the aluminum rod with a stamped cap at this corner position. The top 2' of the rod was bent and attempts to straighten it were unsuccessful. The steel fence post was found to the west, tipped and frozen into the ground. Geodetic coordinates were established on the monument. This corner position was witnessed as shown on the face of this document.

I accept this position as the best evidence as to the location of the original GLO position. Proper methods were utilized in the establishment of the monumented position.

North American Datum 1983 (1996) ± 0.003 Arc seconds
Latitude: 47° 18' 32.239"
Longitude: 93° 50' 54.544"