

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 133 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 6 Corner common to sections 5, 6 AND 31: 32-134-29



EXISTING SURVEYS

Original Government Survey
Year surveyed 1858
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Aspen
<u>BL. OAK</u>	<u>BL. OAK</u>	<u>BL. OAK</u>	<u>Aspen</u>
<u>9"</u>	<u>8"</u>	<u>8"</u>	<u>4"</u>
<u>554E</u>	<u>N 52 W</u>	<u>N 35 1/4 E</u>	<u>54 1/2 W</u>
<u>370 LKS</u>	<u>137 LKS</u>	<u>230 LKS</u>	<u>53 LKS</u>

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration
Year surveyed 1912 By JOHN Curo
Location filed COUNTY SURVEY RECORD BOOK "A" P 434-443
Monument SET 3X3X36" OAK Post
1918 - E.B. HARST - COUNTY BOOK "C" P 128 FND
Curo's stake - SET 2X48" LIM
1921, JOHN GREEN, BOOK "C" P 448 FND CORNER.

Evidence of Subsequent Corner Restoration
Year of search 1960 By Min. DNR - Engineering
Fnd 2" lim.

Species	Bearing	Distance
<u>OAK</u>	<u>OAK</u>	_____
<u>6"</u>	<u>6"</u>	_____
<u>S 9-43W</u>	<u>S 46-38E</u>	_____
<u>49.40'</u>	<u>38'</u>	_____

Species	Bearing	Distance
<u>oak</u>	<u>oak</u>	<u>oak</u>
<u>10"</u>	<u>14"</u>	<u>8"</u>
<u>SW</u>	<u>W.</u>	<u>NE</u>
<u>94.8'</u>	<u>166.1'</u>	<u>84.1'</u>

A-5

Subsequent Corner Restoration
Year surveyed 1970 By Co Hwy Dept
Location filed Co RD #18
Monument 2" lim. in place P.I. roads N-S-E
10" Poplar - NW 58.4'
6" Birch W 61.9'

Evidence of Subsequent Corner Restoration Found
Year of search Dec 2002 By J. Kramer #23668
Cert. of Sur shows mon. found
May 2004 J. Leas #42619
Cert. of Sur. Shows mon. found

1971 - Co Hwy Dept - Co RD #18
2" lim. in place in 1974 set 1" lim.
6" R. oak NE 89.4'
6" oak ESE 119.0'
Power Pole SE 72.3'

1999 - CCSO - Fnd. impl. 2" ODIP 11" E of & Co. RD. 18
down 0.3' in bit. Located 1/4 E of Lynch
LK. Rd. and 11' S of E Ent. to the west.
Ties:
P. Pole N 73° W 71.60'
P. Pole N 74° E 61.20'
12" Twin R. Oak S 78° E 109.16'
8" R. Oak S 66° W 122.00'

2000 AUG - CCSO
Fnd. P.K. in place post overlay constr.
✓ w/ existing ties.