


Index No. C 5

CASS COUNTY LAND CORNER RECORD

T. 133 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 6 Corner common to sections 5 and 6



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1870  
Original monument POST

**Bearing Trees**

Species	<u>N. PINE</u>	<u>N. PINE</u>	
Diameter	<u>8"</u>	<u>6"</u>	
Bearing	<u>N 5E</u>	<u>SRSE</u>	
Distance	<u>320 LKS</u>	<u>230 LKS</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1912 By JOHN CURO  
Location filed COUNTY SURVEY RECORD BOOK A" P434-443  
Monument PUL IRON BOLT SET BY MANKSTER FROM OLD  
WOOD BITS SET 4x3/16" I.M. IN CONCRETE

**Evidence of Subsequent Corner Restoration**

Year of search 1911 By H.W. Mankster  
Microfilm - Roll 10.5 BK 49 P. 50  
End NE Bot. standing green and stub  
of SE Bot. set 1/2 x 1/4" bolt

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

C-5

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search 1999 By CCSO  
End incl. mag/gear P.K. 1' W & CO. RD. 18  
flush w/ bit.  
TIES: P. Pole S 50° W 65.90'  
RLS 13336 Capped I.P. EAST 54.61'  
10' R. Oak S 55° E 106.79'

2000 AUG. - CCSO  
From ties reset a MAG NAIL post.  
Overlay.

Dec. 2002 J. Kramer # 25668  
Cert. of Sur. shows mon. found

May 2004 J. Leas # 42619  
Cert. of Sur. shows mon. found

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_