


Index No. E 9

CASS COUNTY LAND CORNER RECORD

T. 133 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 8 Corner common to sections 4, 5, 8, 9



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1870  
 Original monument POST

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Bearing Trees**  
 Species BR. OAK TAM  
 Diameter 24" 6"  
 Bearing S 31E N 89E  
 Distance 530 LKS 640 LKS

**Original Bearing Trees Found**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed 1915 By JOHN CURD  
 Location filed COUNTY BOOK "B" P. 422-432  
 Monument FIND POST IN RIVER ALSO, 24" OAK  
S 31E 530 LKS  
1918 - E.B. HIRST - COUNTY BOOK "C" P. 127 FIND FENCE POST  
SET FROM GALT BITS - ONE IS STILL IN PLACE.

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Bearing Trees, Reference Objects**  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

E-9

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument MAY 2004 J. Nielsen # 11865  
cert. of sur. shows mon. found  
April 2003 J Nielsen # 11865  
cert. of survey shows monument found

Year of search \_\_\_\_\_ By \_\_\_\_\_