


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ by _____

Original monument _____

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Certificate of Location of Government Corner filed in Cass County

By _____

Recorders Office as Document _____

Date _____

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 133 R. 29 M. 5TH Coordinates: X _____ Y _____
N/4 16 Corner common to sections 9 & 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
 Original monument POST

Original Evidence Found

Year of search 1972 By D. ANDERSON
 Monument found PK/MAG. READING

Species	Bearing	Trees
<u>ASPEN</u>	<u>BL. PINE</u>	
Diameter <u>8"</u>	<u>10"</u>	
Bearing <u>STE</u>	<u>N40E</u>	
Distance <u>20 LKS.</u>	<u>18 LKS.</u>	

Species	Bearing	Trees
<u>R. OAK</u>	<u>R. OAK</u>	<u>POWER PILE</u>
Diameter <u>8"</u>	<u>12"</u>	
Bearing <u>NE</u>	<u>SE</u>	<u>SW</u>
Distance <u>44.74</u>	<u>41.07</u>	<u>39.50</u>

ALL W/ BT TAGS

Subsequent Corner Restoration

Year surveyed 1918 By E. B. HORST
 Location filed COUNTY BOOK "C" P. 130
 Monument SET 2x48" IRON MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 1982 By G. HWY'S SURVEYOR
FND REDHEAD SET OVER 1 3/4 x 3/8" WALL POINT, (6" BEARON OFF) NO 2" IRON - BELIEVE THIS TO BE IRON SET IN 1918 - ALSO FND DEAN ANDERSON'S TIES B.T. TIES LOCATED & VERIFIED

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>R. OAK</u>	<u>8"</u>	<u>NE</u>	<u>44.74'</u>
<u>R. OAK</u>	<u>12"</u>	<u>SE</u>	<u>41.07'</u>
<u>P.P.</u>		<u>SW</u>	<u>39.50'</u>

J-11

Subsequent Corner Restoration

Year surveyed 8/03 By B. Gruna #17253
 Location filed _____
 Monument PK nail fits CCSO ties, a cut L was filed showing 1999 witness trees.

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By CCSO
fd. impl. 3/4" pin (top slightly mushroomed) flush w/ bit. Located @ cor. 36.

REF. TIES:

<u>13" R. Oak</u>	<u>N 45° W</u>	<u>83.53'</u>
<u>9" R. Oak</u>	<u>N 51° E</u>	<u>63.95'</u>
<u>10" R. Oak</u>	<u>S 40° E</u>	<u>62.85'</u>
<u>11" J. Pine</u>	<u>S 44° W</u>	<u>72.48'</u>

D. Anderson # 3091
plot of svy shows mon. found

June 2003 J. Hansen #14712
cert. of svy. shows mon. found

April 2004 J. Hansen #14712
cert. of svy. shows mon. found

Remonumentation certificate prepared 473003
 Filed at CCRO

By *17253
 Date 9/3/03