


Index No. V 7-8

CASS COUNTY LAND CORNER RECORD

T. 133 R. 29 M. 5th Coordinates: X _____ Y _____

MC Corner common to sections 29, 32

WEST Shore ISLAND



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1949 RESURVEY By B.L.M. (CRAWFORD)

Location filed SEC. OF STATE

Monument 2" IRON POST 3' LONG WITH BRASS CAP.

~~T 133N~~
~~S 29~~
M.C. 532
~~1949~~
1949

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>HACKBERRY</u>	<u>ELM</u>
Diameter	<u>9"</u>	<u>9"</u>
Bearing	<u>N 10 1/4 E</u>	<u>S 30 1/4 E</u>
Distance	<u>34 LKS</u>	<u>31 LKS</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____