Index No. V 8-9

CASS COUNTY LAND CORNER RECORD

T. 133 R. 29 M. 5TH Coordinates: X _____ Y _____

MC Corner common to sections 29, 32

EAST SHORE OF 1ST ISLAND



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1949 RESURVEY By B.L.M. (CRAWFORD)

Location filed SEC. OF STATE

Monument 2" IRON POST 3' LONG 32" IN GROUND WITH BRASS CAP MARKED: T 133N

S29 \ MC
S32
R29W 1949

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	ELM	ELM
Diameter	7"	8"
Bearing	S36 3/4 W	N 63 1/2 W
Distance	20 1/2 LKS	69 1/2 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____