


Index No. A 23-24

CASS COUNTY LAND CORNER RECORD

T. 133 R. 30 M. 5TH Coordinates: X _____ Y _____
M.C. # 11 Corner common to sections 1 AND 36-134-30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>PINE</u>	<u>PINE</u>	
<u>12"</u>	<u>20"</u>	
<u>S55E</u>	<u>N50E</u>	
<u>44 LKS</u>	<u>221 LKS.</u>	

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____