Index No. E-F 21

CASS COUNTY LAND CORNER RECORD

T. 133 R. 30 M. 5TH Coordinates: X _____ Y _____

M. C. # 9 Corner common to sections 11 AND 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	N. PINE	BL. PINE		
Diameter	22"	8"		
Bearing	N80E	S68W		
Distance	6 LKS	25 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - SYLVAN BEACH

JOHN CURO 1924

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____