


T. 133 R. 30 M. 5th Coordinates: X _____ Y _____
N1/4 18 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
 Original monument POST

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Bearing Trees

Species	<u>BL. PINE</u>	<u>BL. PINE</u>	_____
Diameter	<u>8"</u>	<u>7"</u>	_____
Bearing	<u>S70 W</u>	<u>N32W</u>	_____
Distance	<u>21 LKS</u>	<u>12 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 7/97 By Central MN Surv.
 Location filed _____
 Monument Set capped iron pin PLS #17253, on line between NE & NW corners.

Evidence of Subsequent Corner Restoration

Year of search 3/03 By B. Grivna
Found capped iron pin, 25' E N. of Hwy #210 and 6' E W. of 43rd Ave. A Cert was filed

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>P. Pole</u>	<u>Tel Ped</u>	<u>R. Pine</u>	<u>Cor Post</u>
<u>NNW</u>	<u>Center</u>	<u>12"</u>	<u>South</u>
<u>50.30'</u>	<u>104.88'</u>	<u>118.19'</u>	<u>106.50'</u>

J-3

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
 Location filed _____
 Monument May 2003 B. Grivna #17253 Cert. of Surv. shows mon. found
April 2004 B. Grivna #17253 (cert. of Surv. shows mon. found)
Oct. 2003 B. Grivna #17253 (cert. of Surv. shows mon. found)

Year of search _____ By _____

