


T. 133 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 17 Corner common to sections 8, 17



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument Post

Species	Bearing	Trees
<u>Bl. Pine</u>	<u>Bl. Pine</u>	
Diameter <u>8"</u>	<u>8"</u>	
Bearing <u>S37W</u>	<u>S43E</u>	
Distance <u>58 LKS</u>	<u>42 LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1950 By Calhoun Dept
 Location filed CRD # 1
 Monument 1" iron monument

Evidence of Subsequent Corner Restoration
 Year of search 1984 By Comstock & Davis
 Certificate Filed Doc # 276576
Find iron pin-set Co. Cast iron

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

P.P.	J. Pine	J. Pine	P.P.
<u>spike</u>	<u>12"</u>	<u>4"</u>	<u>spike</u>
<u>NE</u>	<u>SE</u>	<u>SW</u>	<u>NW</u>
<u>53.48'</u>	<u>64.80'</u>	<u>52.70'</u>	<u>53.42'</u>

Subsequent Corner Restoration
 Year surveyed 6/99 By MN/Dot
 Location filed CCSO
 Monument 0.5" IP ELS #13336 on E

<u>1/2" Rod</u>	<u>N45°E</u>	<u>108.40'</u>
<u>P. Pole</u>	<u>N42°E</u>	<u>56.73'</u>
<u>5" Twin Spruce</u>	<u>N85°E</u>	<u>84.12'</u>
<u>6" Box Elder</u>	<u>S78°E</u>	<u>93.52'</u>
<u>6" Norway</u>	<u>S36°W</u>	<u>134.83'</u>
<u>Sign Post</u>	<u>N54°W</u>	<u>66.55'</u>

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Certificate - Ron Murphy - Comstock & Davis - 1984
Doc. # 276576

Oct 2003 J. Nielson #11865
Cert of Sur. shows Mon. found

Dec. 2003 J. Kramer #23668
Cert. of Sur. shows mon. found

April 2003 J. Kramer #23668
Cert. of survey shows monument found

Re monumentation certificate prepared #432815
 Filed at CCSO & Recorder

By MN/Dot #23668
 Date 2/9/01