Index No. N21

CASS COUNTY LAND CORNER RECORD

T. 133 R. 30 M. 5TH Coordinates: X _____ Y _____

NE 23 Corner common to sections 13, 14, 23, 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	OAK	OAK	OAK	
Diameter	5"	8"	6"	
Bearing	N26W	N2E	S56E	
Distance	88 LKS	85 LKS	156 LKS	

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO

Location filed COUNTY BOOK "B" P 422-432

Monument FOUND IRON PIPE SET BY CURO

Evidence of Subsequent Corner Restoration

Year of search 1965 By Dean Anderson

Survey for DNR (Map in files)

Set iron pipe

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

April 2004 J. Nielsen # 11865
Cert. of Sur. Shows mon. found

Dec. 2004 J. Nielsen #11865
Cert. of survey shows monument found

May 2005 J. Nielson #11865
Cert. of Survey shows mon. found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____