


T. 133 R. 30 M. 5th Coordinates: X _____ Y _____
NE 24 Corner common to sections 13, 24 AND 18, 19 - 133-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument lost

Species	Bearing	Trees
<u>PINE</u>	<u>PINE</u>	<u>PINE</u>
<u>12"</u>	<u>8"</u>	<u>14"</u>
<u>N 85 1/2 W</u>	<u>S 89 1/2 E</u>	<u>N 66 E</u>
<u>397 LKS</u>	<u>304 LKS</u>	<u>634 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK "A" P. 434-443
Monument SET 4x4x36" I.P. IN CONCRETE
1915, JOHN CURO BOOK "B" P. 422-432 FWD IRON
SET BY CURO

Evidence of Subsequent Corner Restoration

Year of search 1998 By CCSO
Fd. I.P. down 0.4' I.P. is 4.0' East & 36
and 5.7' N of & SILVAN OAKS RD.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

P. Pole	T. Ped	T. Pole (1977 tie)	T. Pole (1977 tie)
<u>N 52° W</u>	<u>S 58° W</u>	<u>N 30° E</u>	<u>S 25° E</u>
<u>49.65'</u>	<u>73.00'</u>	<u>70.25'</u>	<u>104.75'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument Jul 2001 J. Hanson #14712
Crtd. of svy shows mon. found.
- corner GPS 11/4/02 CCSO
Attn. cap. down 12' on & #104,
3' E. of 95th Ave.
PK on & & CR. #36 & 132nd st.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____